



FYIORVW

report date: 2024-03-28

General information

Make	NISSAN
Model	CABSTAR 35.13 MWB SHR PU 130
Colour	Red
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	270 Nm at 1.800 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-22
Pictures	13
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-20
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	34
Total items failed	28

MOT #17	2024-03-21 11:30
MOT test number	311526405630
Result	✓ Passed
Next expiry date	2025-03-20

MOT #16	2022-12-28 11:08
MOT test number	793471261802
Result	✓ Passed

MOT #15	2022-12-28 11:04
MOT test number	986683893772
Result	✗ Failed
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #14**

2021-09-18 09:11

**MOT test number**

105116198033

**Result**

✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13**

2021-09-18 09:11

**MOT test number**

301676455485

**Result**

✗ Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Pass with rectification** Offside Front Side repeater not working (4.4.1 (a) (ii))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12**

2019-10-24 15:04

**MOT test number**

969934690546

**Result**

✓ Passed

**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Park brake effort on limit**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both D bushes (5.3.4 (a) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #11**

2019-10-24 08:14

**MOT test number**

513285784238

**Result****✗ Failed**

**Fail** Nearside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both D bushes (5.3.4 (a) (i))

**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice** Park brake effort on limit

**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #10**

2018-11-07 14:18

**MOT test number**

445652712895

**Result****✓ Passed**

**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #9**

2018-11-06 15:17

**MOT test number**

953252495491

**Result****✗ Failed**

**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #8**

2017-10-31 16:45

**MOT test number**

814851561773

**Result****✓ Passed**

**Advice** Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #7	2017-10-17 14:19
MOT test number	168255727414
Result	✗ Failed
Fail	Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
Fail	Offside Front Lower Shock absorber has an excessively worn bush (2.7.4)
Fail	Rear fog lamp tell tale not working (1.3.1b)
Fail	Offside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)
Advice	Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
Fail	Nearside Front Lower Shock absorber has an excessively worn bush (2.7.4)
Fail	Offside Rear fog lamp not working (1.3.2b)
Fail	Nearside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)
Fail	Nearside Rear Brake hose leaking (3.6.A.1)
Fail	Offside rear parking brake recording little or no effort (3.7.B.6a)
Fail	Nearside Front suspension has excessive play in a upper suspension ball joint (2.5.B.1a)

MOT #6	2016-07-04 12:07
MOT test number	615040346953
Result	✓ Passed

**MOT #5**

2015-04-02 18:15

**MOT test number**

497032695065

**Result**

✓ Passed

**Advice** Nearside Front Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Offside Front Lower Ball joint has slight play (2.2.B.1f)**Advice** Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)**MOT #4**

2015-04-01 10:26

**MOT test number**

148801095417

**Result**

✗ Failed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Lower Ball joint has slight play (2.2.B.1f)**Advice** Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3**

2014-04-05 11:28

**MOT test number**

188685194480

**Result**

✓ Passed

**Advice** Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)



MOT #22014-04-02 12:56

MOT test number917442694008

ResultX Failed

AdviceOffside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

FailFront Exhaust has a major leak of exhaust gases (7.1.2)

FailOffside Rear Lower Shock absorber has an excessively worn bush (2.7.4)

FailOffside Front Lower Shock absorber has an excessively worn bush (2.7.4)

AdviceRear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

FailNearside Rear Lower Shock absorber has an excessively worn bush (2.7.4)

FailNearside Front Lower Shock absorber has an excessively worn bush (2.7.4)

FailNearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

MOT #12013-03-14 14:10

MOT test number938113573044

Result✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
20 March 2025

<b>Tax status</b>	Valid until 1 March
-------------------	---------------------

<b>Days left</b>	307
------------------	-----

<b>MOT expiry date</b>	20 March 2025
------------------------	---------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-31
Last registration	2024-03-21
Complete history	<a href="#">See info</a>



Registration #1	2010-03-31	9 mi
Registration #2	2013-03-14	37.247 mi
Registration #3	2014-04-02	57.696 mi
Registration #4	2014-04-05	57.700 mi
Registration #5	2015-04-01	75.507 mi
Registration #6	2015-04-02	75.508 mi
Registration #7	2016-07-04	90.923 mi
Registration #8	2017-10-17	109.950 mi
Registration #9	2017-10-31	109.953 mi
Registration #10	2018-11-06	113.060 mi
Registration #11	2019-05-29	121.277 mi
Registration #12	2019-05-29	121.277 mi
Registration #13	2019-05-29	121.277 mi
Registration #14	2019-05-29	121.277 mi
Registration #15	2019-05-29	121.277 mi
Registration #16	2019-05-29	121.277 mi
Registration #17	2019-05-29	121.277 mi
Registration #18	2019-05-29	121.277 mi
Registration #19	2019-05-29	121.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1900 mm
Kerb weight	1978 kg
Max. allowed weight	3500 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	634177