



report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 SE LUX AWD
Colour	Black
Year of manufacture	2012
Top speed	127 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.5 mpg
CO2 emission	219 g/km
CO2 label	K







Internet history

Entry 1

Date	2021-05-26
Pictures	25
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-30
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	21
Total items failed	0

MOT #10 2023-05-10 15:24

MOT test number 663117418401

Result ✓ Passed

Next expiry date 2024-05-30

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Slight play in steering inner rack joints**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9 2022-05-27 16:17

MOT test number 150581511911

Result ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2022-05-27 10:56**MOT test number** 495250872565**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Rear Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2021-05-31 11:44**MOT test number** 237929435282**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge N/S and O/S (5.2.3 (e))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2020-10-28 16:02**MOT test number** 641937110778**Result** ✓ Passed**MOT #5** 2019-10-16 14:49**MOT test number** 787454779644**Result** ✓ Passed



MOT #4	2018-10-23 13:46
MOT test number	252484790942
Result	✓ Passed
MOT #3	2017-07-20 10:30
MOT test number	497000600668
Result	✓ Passed
MOT #2	2016-07-21 14:10
MOT test number	641790574720
Result	✓ Passed
MOT #1	2015-07-10 10:45
MOT test number	848741495176
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
30 May 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	30 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 AK12NDY
Plate since	2024-03-29
Current registration	 AK12NDY
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-07-10
Last registration	2023-05-10
Complete history	See info



Registration #1	2012-07-10	16 mi
Registration #2	2015-07-10	51.299 mi
Registration #3	2016-07-21	64.711 mi
Registration #4	2017-07-20	78.587 mi
Registration #5	2018-10-23	93.509 mi
Registration #6	2019-10-16	107.913 mi
Registration #7	2020-05-20	121.317 mi
Registration #8	2021-05-20	134.721 mi
Registration #9	2022-05-20	148.125 mi
Registration #10	2023-05-10	161.529 mi
Registration #11	2023-05-10	174.933 mi
Registration #12	2023-05-10	188.337 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2112 mm
Height	1784 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2158 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1139303