



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D XT-R AWD
Colour	Beige
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	340 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 2

Date	2023-12-14
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-10-30
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-03-22
-----------------	------------

MOT pass rate	69 %
---------------	------

MOT passed	9
------------	---

Failed MOT tests	4
------------------	---

Total advice items	21
--------------------	----

Total items failed	10
--------------------	----

MOT #13	2024-03-23 12:10
---------	------------------

MOT test number	621530856127
-----------------	--------------

Result	✗ Failed
--------	----------

Fail Prop shaft bearing excessively worn (6.1.7 (b) (i))

Advice Nearside Play in steering rack inner joint(s)

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Electronic stability control warning lamp indicates a fault (7.12 (e))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #12	2023-03-18 09:12
---------	------------------

MOT test number	336712415741
-----------------	--------------

Result	✓ Passed
--------	----------

Advice Prop shaft bearing has slight play (6.1.7 (b) (i))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #11** 2022-03-23 12:50**MOT test number** 693473965978**Result** ✓ Passed

- Advice** Front Lower Suspension arm ball joint has slight play both sides (5.3.4 (a) (i))
- Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2021-03-18 14:47**MOT test number** 269861793407**Result** ✓ Passed**MOT #9** 2020-01-29 10:14**MOT test number** 147233915269**Result** ✓ Passed

- Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8 2019-01-31 10:40**MOT test number** 974404327493**Result** ✓ Passed**MOT #7** 2019-01-31 10:40**MOT test number** 454681015983**Result** ✗ Failed

- Pass with rectification** Offside Front All position lamps not working (4.2.1 (a))

**MOT #6** 2018-02-05 12:10**MOT test number** 290705082102**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #5** 2017-02-08 12:43**MOT test number** 354248330273**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front tyre has a sharp object in tyre**Advice** Front brake disc worn, pitted or scored, but not seriously weakened nearside and offside (3.5.1i)**MOT #4** 2017-02-06 16:29**MOT test number** 112029975356**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front tyre has a sharp object in tyre**Advice** Front brake disc worn, pitted or scored, but not seriously weakened nearside and offside (3.5.1i)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #3** 2016-02-08 16:56**MOT test number** 141729636131**Result** ✓ Passed**Advice** Rear Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened corroded (3.5.1i)



MOT #2	2016-02-08 16:02
MOT test number	198964049138
Result	✗ Failed
Advice	Rear Inner Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened corroded (3.5.1i)
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Offside Rear Shock absorber has a serious fluid leak (2.7.3)

MOT #1	2015-02-11 13:59
MOT test number	385642645005
Result	✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	DN61YRX
Plate since	2019-09-29
Current registration	DN61YRX
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-12-23
Last registration	2024-03-23
Complete history	See info



Registration #1	2011-12-23	21 mi
Registration #2	2015-02-11	59.773 mi
Registration #3	2016-02-08	74.223 mi
Registration #4	2016-02-08	74.223 mi
Registration #5	2017-02-06	88.221 mi
Registration #6	2017-02-08	88.221 mi
Registration #7	2018-02-05	101.217 mi
Registration #8	2019-01-31	113.223 mi
Registration #9	2019-01-31	113.223 mi
Registration #10	2019-01-31	113.223 mi
Registration #11	2019-01-31	113.223 mi
Registration #12	2019-01-31	113.223 mi
Registration #13	2019-01-31	113.223 mi
Registration #14	2019-01-31	113.223 mi
Registration #15	2019-01-31	113.223 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4365 mm
Wheel base	2560 mm
Kerb weight	1650 kg
Max. allowed weight	2190 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	2AD0374569
---------------	------------