





General information

Make	MERCEDES
Model	S-Class S500
Colour	Grey
Year of manufacture	2008
Top speed	155 mph
0 - 60 mph	5.4 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	382 BHP
Max. torque	529 Nm at 2.800 rpm
Engine capacity	5.461 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.1 mpg
Consumption extra urban	32.8 mpg
Consumption combined	23.9 mpg
CO2 emission	281 g/km
CO2 label	Μ







Internet history

Entry 3

Date

Pictures

Listing price

2022-03-22 8

Ŭ

View report



source: cargurus.co.uk

Entry 2	
Date	2022-02-07
Pictures	1
Listing price	View report



source: autotrader.co.uk

Entry 1	
Date	2021-12-13
Pictures	21
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-28
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	24
Total items failed	2

MOT #14	2023-06-24 10:43
MOT test number	540264455937
Result	✓ Passed
Next expiry date	2024-06-28
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))	
Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))	

MOT #13	2022-06-29 12:34
MOT test number	858870735702
Result	✓ Passed

MOT #12	2021-09-07 12:02
MOT test number	220678670192
Result	✓ Passed



MOT #11

BA28000
report date: 2024-03-29
2020-09-07 10:15
573668863901

MOT test number	573668863901
Result	✓ Passed
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated near joint dust cover (5.3.4 (b) (i))	[·] side caster arm ball
Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Front Lower Suspension arm ball joint has slight play near side front joint has slight play (5.3.4 (a) (i))	lower spring link ball

MOT #10		2019-05-22 08:27
MOT test	number	135370557826
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Exhaust silencer slightly loose (8.1.1 (b) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9	2018-05-21 10:47
MOT test number	153667720807
Result	✓ Passed

MOT #8	2016-12-13 10:05
MOT test number	299416639522
Result	✓ Passed

MOT #7	2016-03-02 16:15
MOT test number	792024443542
Result	✓ Passed



MOT #6	2016-02-26 16:40
MOT test number	618203129938
Result	🗙 Failed
Advice Wiperblades worn	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in (2.4.G.2)	excessive movement
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in (2.4.G.2)	n excessive movement

MOT #5		2015-03-03 14:13
MOT test	number	127692365089
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	
Notice	Nsf tyre worn outer edge	

MOT #4	2014-05-16 10:52
MOT test number	749936634139
Result	Passed
Notice NSF Tyre worn on outer edge.	
Advice Nearside Front wheel bearing has slight play (2.5.A.3c)	

MOT #3		2013-09-25 15:34
MOT test	number	805338763203
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #2	2012-09-25 09:36
MOT test number	976319162262
Result	✓ Passed
MOT #1	2011-10-03 12:41
MOT test number	207756571286
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	✓ MOT Expires: 28 June 2024
Tax status	Valid until 1 September
Days left	124
MOT expiry date	28 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Μ
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	VAMPLE
Date	
Category	AMP
Туре	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
See in this check in this MERCEDES had uncreate humber plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Carrent registration	
Carrent registration Plate since	





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-01
Last registration	2023-06-24
Complete history	See info



Registration #1	2008-09-01	10 mi
Registration #2	2011-10-03	18.675 mi
Registration #3	2012-09-25	24.448 mi
Registration #4	2013-09-25	31.982 mi
Registration #5	2014-05-16	36.769 mi
Registration #6	2015-03-03	41.991 mi
Registration #7	2016-02-26	48.908 mi
Registration #8	2016-03-02	48.908 mi
Registration #9	2016-12-13	53.555 mi
Registration #10		11.777 est
Registration #11		11.777 esi
Registration #12		11.777 est
Registration #13		11.777 est
Registration #14		11.777 est
Registration #15		11.777 est
Registration #16		01.707 est
Registration #17		11.777 mi
Registration #18		11.117 est



BV580G0 report date: 2024-03-29

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1872 mm
Height	1473 mm
Length	5206 mm
Wheel base	3165 mm
Kerb weight	1985 kg
Additional information	
Additional information Fuel tank capacity	90 l
	90 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 4