



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO D-4D T2
Colour	Grey
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-08
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-07-19
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	65
Total items failed	15

MOT #18 2023-07-20 18:11

MOT test number 534108270235

Result ✓ Passed

Next expiry date 2024-07-19

**Advice** Brake pad(s) wearing thin Cannot assess life of pads all round due to wheel trims at time of test have advised presenter (1.1.13 (a) (ii))

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Rear Handbrake travel RBT ok

**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement Both rear trailing arms worn have advised presenter (5.3.4 (a) (i))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17 2023-07-20 18:11

MOT test number 144247258049

Result ✗ Failed

**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement Both rear trailing arms worn have advised presenter (5.3.4 (a) (i))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Rear Handbrake travel RBT ok

**Advice** Brake pad(s) wearing thin Cannot assess life of pads all round due to wheel trims at time of test have advised presenter (1.1.13 (a) (ii))

**MOT #16**

2022-04-27 10:29

**MOT test number**

311436379838

**Result**

✓ Passed

- Advice** Nearside Rear Nail in tyre
- Advice** Undertray damaged
- Advice** Nearside Rear Suspension component pin or bush slightly worn trailing arm (5.3.4 (a) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))
- Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Items removed from driver's view prior to test
- Advice** Handbrake close to end of travel
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Brake pad(s) wearing thin both front (1.1.13 (a) (ii))
- Advice** Offside Rear Suspension component pin or bush slightly worn trailing arm (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #15**

2021-04-29 11:57

**MOT test number**

481174629983

**Result**

✓ Passed

- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #14**

2021-04-29 11:57

**MOT test number**

742104176057

**Result****✗ Failed**

- Pass with rectification** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Pass with rectification** Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))
- Pass with rectification** Brake lever has insufficient reserve travel (1.1.2 (a))
- Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #13**

2020-03-07 15:22

**MOT test number**

509228933098

**Result****✓ Passed**

- Advice** Rear Brake disc worn, but not excessively offside and nearside (1.1.14 (a) (i))
- Advice** Front Brake pad(s) wearing thin offside and nearside (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, but not excessively offside and nearside (1.1.14 (a) (i))

**MOT #12**

2019-02-09 14:34

**MOT test number**

153637982721

**Result****✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front brake discs lipped

**MOT #11** 2018-02-10 12:53**MOT test number** 746512747915**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #10** 2018-02-07 10:52**MOT test number** 630752267987**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Front Windscreen wiper does not clear the windscreen effectively split (8.2.2)**MOT #9** 2017-02-01 14:05**MOT test number** 827269740898**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)

**MOT #8** 2016-01-18 12:29**MOT test number** 887269313339**Result** ✓ Passed**Advice** Service & Parking brakes have only just met the requirements.**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2015-02-06 12:02**MOT test number** 365687135079**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Under-trays fitted obscuring some underside components**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



**MOT #6** 2014-02-13 09:39**MOT test number** 396914644031**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2013-03-01 10:26**MOT test number** 816030563000**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** N/s wiper blade rubber starting to split.**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #4** 2013-03-01 10:26**MOT test number** 619090063099**Result** ✗ Failed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** N/s wiper blade rubber starting to split.**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Engine covers fitted obscuring some components in the engine bay**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #3** 2012-02-17 12:41**MOT test number** 675188642029**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Oil level low topped up before test.**MOT #2** 2011-02-23 13:57**MOT test number** 656324951087**Result** ✓ Passed**Notice** Nail in offside rear tyre**MOT #1** 2011-02-23 13:57**MOT test number** 189344051087**Result** ✗ Failed**Pass with rectification** Emissions not tested (7.0)**Notice** Nail in offside rear tyre



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
19 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	19 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-01
Last registration	2023-07-20
Complete history	<a href="#">See info</a>



Registration #1	2008-03-01	22 mi
Registration #2	2011-02-23	48.126 mi
Registration #3	2012-02-17	67.095 mi
Registration #4	2013-03-01	86.119 mi
Registration #5	2014-02-13	101.843 mi
Registration #6	2015-02-06	116.079 mi
Registration #7	2016-01-18	126.801 mi
Registration #8	2017-02-01	148.428 mi
Registration #9	2018-02-07	161.057 mi
Registration #10	2019-05-20	161.057 mi
Registration #11	2020-05-20	161.057 mi
Registration #12	2021-05-20	161.057 mi
Registration #13	2022-05-20	161.057 mi
Registration #14	2023-05-20	161.057 mi
Registration #15	2024-05-20	161.057 mi
Registration #16	2025-05-20	161.057 mi
Registration #17	2026-05-20	161.057 mi
Registration #18	2027-05-20	161.057 mi

More info >





Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	2AD5364188