




report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX LX
Colour	Blue
Year of manufacture	2007
Top speed	122 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg
CO2 emission	194 g/km
CO2 label	J





MOT history

MOT expiry date	2021-05-01
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	30
Total items failed	18

MOT #18	2020-05-02 10:51
MOT test number	983716692993
Result	✓ Passed
Next expiry date	2021-05-01
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Front Headlamp lens slightly defective both (4.1.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

MOT #17	2019-03-14 11:04
MOT test number	380309777103
Result	✓ Passed

MOT #16	2019-03-13 13:23
MOT test number	109099083456
Result	✗ Failed
Fail	Offside Front Prop shaft joint constant velocity boot missing (6.1.7 (g) (ii))
Fail	Front Tyre tread depth below requirements of 1.6mm both sides (5.2.3 (e))
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #15** 2018-02-17 13:09**MOT test number** 212209907763**Result** ✓ Passed**MOT #14** 2018-02-17 12:06**MOT test number** 125218561959**Result** ✗ Failed**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**MOT #13** 2017-02-09 15:24**MOT test number** 878427648154**Result** ✓ Passed**Advice** Offside Rear tyre inner edge worn**Advice** Both front tyre`s inner edge`s worn**Advice** Front brake disc worn, pitted or scored, but not seriously weakened corroded (3.5.1i)**MOT #12** 2017-02-09 10:16**MOT test number** 319001066581**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened corroded (3.5.1i)**Fail** Nearside Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Both front tyre`s inner edge`s worn**Fail** Offside Rear Rear reflector missing (1.5.1a)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Pass with rectification** Offside Front Direction indicator incorrect colour (1.4.A.2f)**Advice** Offside Rear tyre inner edge worn

**MOT #11** 2016-02-10 10:30**MOT test number** 600026836931**Result** ✓ Passed**Advice** Offside front tyre inner edge slightly worn**Advice** Front brake disc worn, pitted or scored, but not seriously weakened corroded (3.5.1i)**Advice** Offside rear tyre inner edge worn**MOT #10** 2015-02-09 16:22**MOT test number** 295330345088**Result** ✓ Passed**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Notice** Both rear tyres inner and outer edges worn**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2015-02-09 10:13**MOT test number** 356230545094**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Fail** Offside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Notice** Coolant level low**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Both front tyres inner and outer edges worn

**MOT #8** 2014-02-11 09:53**MOT test number** 179492944401**Result** ✓ Passed

- Notice** Nearside front tyre inner and outer edges worn
- Notice** Offside rear tyre outer side wall slightly damaged
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Offside front tyre inner and outer edges worn

MOT #7 2014-02-11 08:00**MOT test number** 177872844019**Result** ✗ Failed

- Notice** Offside front tyre inner and outer edges worn
- Fail** Front registration plate deteriorated (6.3.1d)
- Notice** Nearside front tyre inner and outer edges worn
- Fail** Front registration plate insecure (6.3.1b)
- Notice** Offside rear tyre outer side wall slightly damaged
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6 2013-02-11 14:57**MOT test number** 228092143038**Result** ✓ Passed

**MOT #5** 2013-02-11 10:00**MOT test number** 777142543082**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Both fron tyres inner and outer edges worn**MOT #4** 2012-02-08 12:26**MOT test number** 518979532034**Result** ✓ Passed**MOT #3** 2011-02-16 16:52**MOT test number** 548097741014**Result** ✓ Passed**MOT #2** 2010-02-01 09:57**MOT test number** 403232330019**Result** ✓ Passed**MOT #1** 2010-02-01 09:57**MOT test number** 692432030083**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Offside Steering system has a road wheel fouling a part of the vehicle (2.2.D.2a)



Tax & MOT check

×
Untaxed

Tax expired:
14 December 2020

×
MOT

Expired:
1 May 2021

Tax status

Expired at 14 December 2020

Days left

1231 days too late

MOT expiry date

1 May 2021

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-03-23
Last registration	2020-05-02
Complete history	See info



Registration #1	2007-03-23	20 mi
Registration #2	2010-02-01	13.854 mi
Registration #3	2011-02-16	23.139 mi
Registration #4	2012-02-08	37.402 mi
Registration #5	2013-02-11	51.328 mi
Registration #6	2013-02-11	51.328 mi
Registration #7	2014-02-11	61.959 mi
Registration #8	2014-02-11	61.959 mi
Registration #9	2015-02-09	72.098 mi
Registration #10	2015-02-09	72.098 mi
Registration #11	2015-02-09	72.098 mi
Registration #12	2015-02-09	72.098 mi
Registration #13	2015-02-09	72.098 mi
Registration #14	2015-02-09	72.098 mi
Registration #15	2015-02-09	72.098 mi
Registration #16	2015-02-09	72.098 mi
Registration #17	2015-02-09	72.098 mi
Registration #18	2015-02-09	72.098 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	7K39866