



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	AVENSIS VVTI COLOUR COLLECTION
Colour	Silver
Year of manufacture	2006
Top speed	124 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	171 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-05-22
Pictures	19
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-04-23
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	58
Total items failed	7

MOT #23	2024-04-24 11:10
MOT test number	869209460763
Result	✓ Passed
Next expiry date	2025-04-23
Advice	Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #22	2023-02-20 15:01
MOT test number	951876426543
Result	✓ Passed
Advice	Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #21	2022-03-04 15:03
MOT test number	517815462098
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing Perished / cracked around sidewalls. (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Perished / cracked around sidewalls and tread blocks. (5.2.3 (d) (ii))

**MOT #20**

2022-03-04 13:06

**MOT test number**

640680805717

**Result****✗ Failed**

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Perished / cracked around sidewalls. (5.2.3 (d) (ii))

**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Perished / cracked around sidewalls and tread blocks. (5.2.3 (d) (ii))

**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MAJOR** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #19**

2021-02-19 13:54

**MOT test number**

292061872209

**Result****✓ Passed**

**Advice** Advise center exhaust hanger corroded/nearly broken away from exhaust

**Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18** 2021-02-19 10:03**MOT test number** 502823886471**Result** ✗ Failed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Offside Front Lower Suspension arm corroded and seriously weakened (5.3.3 (b) (i))
- Advice** Advise center exhaust hanger corroded/nearly broken away from exhaust
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17** 2020-02-21 13:50**MOT test number** 856026003255**Result** ✓ Passed

- Advice** Parking brake travel high
- Advice** Rear tyres cracking

**MOT #16** 2020-02-21 12:56**MOT test number** 320810826464**Result** ✗ Failed

- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Rear tyres cracking
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Parking brake travel high

**MOT #15** 2019-02-18 09:55**MOT test number** 778623831520**Result** ✓ Passed**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #14** 2018-02-19 15:21**MOT test number** 287975492856**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Fuel filler lid does not shut**MOT #13** 2018-02-17 10:15**MOT test number** 400759352524**Result** ✗ Failed**Advice** Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Fuel filler lid does not shut**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #12** 2017-02-17 15:51**MOT test number** 239599553068**Result** ✓ Passed

**MOT #11** 2016-02-10 11:52**MOT test number** 159989457933**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #10** 2015-02-06 12:15**MOT test number** 699507835084**Result** ✓ Passed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**MOT #9** 2014-02-12 14:12**MOT test number** 975473244085**Result** ✓ Passed**MOT #8** 2013-02-12 12:16**MOT test number** 339943943050**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Under-trays fitted obscuring some underside components**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front discs worn**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #7**

2013-02-12 12:16

**MOT test number**

246103443005

**Result****✗ Failed****Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Centre Stop lamp not working (1.2.1b)**Notice** Front discs worn**MOT #6**

2012-02-03 12:37

**MOT test number**

135644532474

**Result****✓ Passed****Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #5**

2012-02-03 12:37

**MOT test number**

117884032015

**Result****✗ Failed****Pass with rectification** Centre Stop lamp not working (1.2.1b)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Pass with rectification** Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear coil spring corroded (2.4.C.1b)



**MOT #4** 2011-02-08 14:26**MOT test number** 808499931014**Result** ✓ Passed**Notice** Front number plate damaged but secure and not likely to be misread**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2010-02-08 12:12**MOT test number** 560679030020**Result** ✗ Failed**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Notice** Front number plate cracked but not insecure and lettering still readable**MOT #2** 2010-02-08 12:12**MOT test number** 404539130072**Result** ✓ Passed**Notice** Front number plate cracked but not insecure and lettering still readable**MOT #1** 2009-02-17 13:42**MOT test number** 521858449097**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
23 April 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	23 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-03-01
Last registration	2024-04-24
Complete history	<a href="#">See info</a>



Registration #1	2006-03-01	16 mi
Registration #2	2009-02-17	23.389 mi
Registration #3	2010-02-08	30.149 mi
Registration #4	2011-02-08	36.127 mi
Registration #5	2012-02-03	42.942 mi
Registration #6	2013-02-12	48.416 mi
Registration #7	2014-02-12	55.480 mi
Registration #8	2015-02-06	62.093 mi
Registration #9	2016-02-10	70.063 mi
Registration #10	2017-02-17	77.181 mi
Registration #11	2018-02-17	87.703 mi
Registration #12	2019-02-20	95.227 mi
Registration #13	2020-02-20	102.227 mi
Registration #14	2021-02-20	109.227 mi
Registration #15	2022-02-20	116.227 mi
Registration #16	2023-02-20	123.227 mi
Registration #17	2024-02-20	130.227 mi
Registration #18	2025-02-20	137.227 mi
Registration #19	2026-02-20	144.227 mi
Registration #20	2027-02-20	151.227 mi
Registration #21	2028-02-20	158.227 mi
Registration #22	2029-02-20	165.227 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1480 mm
Length	4630 mm
Wheel base	2700 mm
Kerb weight	1245 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	1ZZU687890