



**DXI4X0A**

report date: 2024-03-28

General information

Make	CITROEN
Model	DS4 HDI DSPORT
Colour	White
Year of manufacture	2014
Top speed	132 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.7 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 2

Date	2023-12-06
Pictures	0
Listing price	<a href="#">View report</a>

source: **carcraft.co.uk**

Entry 1

Date	2021-07-30
Pictures	21
Listing price	<a href="#">View report</a>



source: **autotrader.co.uk**



MOT history

MOT expiry date	2024-11-08
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	20
Total items failed	0

MOT #11	2023-11-09 17:33
MOT test number	444472993769
Result	✓ Passed
Next expiry date	2024-11-08
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10	2023-10-06 10:17
MOT test number	978334200389
Result	✗ Failed
MAJOR	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Minor	Offside Front Tyre obviously under inflated (5.2.3 (I))
MAJOR	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
MAJOR	Offside Front Suspension arm pin or bush excessively worn front suspension arm bush (5.3.4 (a) (i))
MAJOR	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR	Nearside Front Suspension arm pin or bush excessively worn front suspension arm bush (5.3.4 (a) (i))
MAJOR	Front Headlamp aim unable to be tested (4.1.2 (b))

**MOT #9** 2023-09-28 14:27**MOT test number** 353993577850**Result** ✗ Failed**MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Headlamp aim unable to be tested (4.1.2 (b))**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Both front arm bushes are separating**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #8** 2022-08-15 12:27**MOT test number** 212015690343**Result** ✓ Passed**Advice** Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Nearside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #7** 2021-08-22 16:57**MOT test number** 599372997475**Result** ✓ Passed**MOT #6** 2021-02-01 15:33**MOT test number** 542325439904**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #5** 2021-01-29 10:10**MOT test number** 752220800459**Result** ✗ Failed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #4** 2020-01-28 15:09**MOT test number** 432009917128**Result** ✓ Passed**MOT #3** 2019-01-11 11:48**MOT test number** 799135471165**Result** ✓ Passed**MOT #2** 2018-01-21 14:29**MOT test number** 958546255557**Result** ✓ Passed**MOT #1** 2017-03-15 10:25**MOT test number** 337928844961**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
8 November 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	8 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-03-01
Last registration	2023-11-09
Complete history	<a href="#">See info</a>



Registration #1	2014-03-01	24 mi
Registration #2	2017-03-15	52.176 mi
Registration #3	2018-01-21	61.074 mi
Registration #4	2019-01-11	70.439 mi
Registration #5	2020-01-28	78.028 mi
Registration #6	2021-01-29	84.084 mi
Registration #7	2021-02-01	84.162 mi
Registration #8	2022-05-20	95.277 mi
Registration #9	2023-05-20	105.277 mi
Registration #10	2023-05-20	115.277 mi
Registration #11	2023-05-20	125.277 mi
Registration #12	2023-05-20	135.277 mi
Registration #13	2023-05-20	145.277 mi
Registration #14	2023-05-20	155.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	80%
Pedestrian	43%
Safety systems	97%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYZE4124651