



General information

Make	FORD
Model	S-MAX EDGE TDCI
Colour	Silver
Year of manufacture	2010
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-11-13
Pictures	19
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2025-02-08
<b>MOT pass rate</b>	67 %
<b>MOT passed</b>	12
<b>Failed MOT tests</b>	6
<b>Total advice items</b>	31
<b>Total items failed</b>	13

<b>MOT #18</b>	2024-02-09 12:48
<b>MOT test number</b>	240130766041
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-02-08
<b>Advice</b>	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
<b>Advice</b>	Nearside Play in steering rack inner joint(s)

<b>MOT #17</b>	2023-01-24 15:42
<b>MOT test number</b>	673998749215
<b>Result</b>	✓ Passed
<b>Advice</b>	Exhaust has a minor leak of exhaust gases Centre pipe (6.1.2 (a))
<b>Advice</b>	Some play in nearside steering rack tie rod

<b>MOT #16</b>	2023-01-24 15:42
<b>MOT test number</b>	127940226571
<b>Result</b>	✗ Failed
<b>Advice</b>	Exhaust has a minor leak of exhaust gases Centre pipe (6.1.2 (a))
<b>Pass with rectification</b>	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Advice</b>	Some play in nearside steering rack tie rod



<b>MOT #15</b>	2022-02-02 16:57
<b>MOT test number</b>	983778781695
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Tyre worn close to legal limit/worn on edge BOTH 215/60/16 (5.2.3 (e))

<b>MOT #14</b>	2022-02-02 16:57
<b>MOT test number</b>	487763721452
<b>Result</b>	✗ Failed
<b>Advice</b>	Front Tyre worn close to legal limit/worn on edge BOTH 215/60/16 (5.2.3 (e))
<b>Pass with rectification</b>	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

<b>MOT #13</b>	2021-02-06 09:27
<b>MOT test number</b>	812295044230
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush starting to split (5.3.4 (a) (i))
<b>Advice</b>	Offside Rear Child Seat fitted not allowing full inspection of adult belt

<b>MOT #12</b>	2021-01-30 11:46
<b>MOT test number</b>	291740335002
<b>Result</b>	✗ Failed
<b>Minor</b>	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Advice</b>	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush starting to split (5.3.4 (a) (i))
<b>Advice</b>	Offside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Fail</b>	Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt rack gaiter adrift from rack (2.1.3 (g) (ii))

**MOT #11** 2020-02-03 12:12**MOT test number** 373189941704**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt o/s & n/s rear**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2020-01-27 11:20**MOT test number** 937232651572**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Child Seat fitted not allowing full inspection of adult belt o/s & n/s rear**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #9** 2019-01-26 14:01**MOT test number** 985482338943**Result** ✓ Passed



<b>MOT #8</b>	2018-01-24 10:54
<b>MOT test number</b>	400074743001
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside front door sill damaged

<b>MOT #7</b>	2018-01-24 10:54
<b>MOT test number</b>	784733518286
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Offside Headlamp aim too high (1.8)
<b>Advice</b>	Nearside front door sill damaged

<b>MOT #6</b>	2017-01-23 16:48
<b>MOT test number</b>	545441990450
<b>Result</b>	✓ Passed

<b>MOT #5</b>	2016-01-14 16:03
<b>MOT test number</b>	393765520545
<b>Result</b>	✓ Passed
<b>Advice</b>	Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #4** 2016-01-13 13:02**MOT test number** 865248633234**Result** ✗ Failed**Fail** Offside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**MOT #3** 2015-01-10 09:57**MOT test number** 978930715014**Result** ✓ Passed**MOT #2** 2014-01-28 13:21**MOT test number** 519918324015**Result** ✓ Passed**MOT #1** 2013-02-04 10:01**MOT test number** 247525433070**Result** ✓ Passed**Advice** Brake pad(s) wearing thin (3.5.1g)**Notice** N/s/r tyre worn close to minimum**Advice** Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
8 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	8 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-03-01
Last registration	2024-02-09
Complete history	<a href="#">See info</a>



Registration #1	2010-03-01	9 mi
Registration #2	2013-02-04	34.920 mi
Registration #3	2014-01-28	46.389 mi
Registration #4	2015-01-10	54.405 mi
Registration #5	2016-01-13	62.418 mi
Registration #6	2016-01-14	62.420 mi
Registration #7	2017-01-23	72.329 mi
Registration #8	2018-01-24	94.180 mi
Registration #9	2018-01-24	94.180 mi
Registration #10	2019-01-26	115.740 mi
Registration #11	2019-01-26	115.740 mi
Registration #12	2019-01-26	115.740 mi
Registration #13	2019-01-26	115.740 mi
Registration #14	2019-01-26	115.740 mi
Registration #15	2019-01-26	115.740 mi
Registration #16	2019-01-26	115.740 mi
Registration #17	2019-01-26	115.740 mi
Registration #18	2019-01-26	115.740 mi
Registration #19	2019-01-26	115.740 mi
Registration #20	2019-01-26	115.740 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1897 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	9D14145