



report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO HDI VTR PLUS EGS GRAND PICASSO
Colour	Blue
Year of manufacture	2008
Top speed	112 mph
0 - 60 mph	13.4 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	150 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-02-08
Pictures	6
Listing price	<a href="#">View report</a>



source: yesauto.com



MOT history

MOT expiry date	2025-04-07
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	27
Total items failed	24

MOT #20	2024-03-19 16:52
MOT test number	921909024103
Result	✓ Passed
Next expiry date	2025-04-07
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #19	2024-03-19 16:52
MOT test number	810926868440
Result	✗ Failed
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #18	2023-03-15 14:37
MOT test number	617346738768
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #17**

2022-04-08 12:04

**MOT test number**

137681906168

**Result**

✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Nail in tyre**MOT #16**

2022-04-07 08:22

**MOT test number**

598634479829

**Result**

✗ Failed

**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**Fail** Nearside Windscreen washer not working (3.5 (a))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Nail in tyre**MOT #15**

2021-04-08 11:12

**MOT test number**

232605098823

**Result**

✓ Passed

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush (5.3.4 (a) (i))

**MOT #14** 2020-03-06 15:03**MOT test number** 729203553765**Result** ✓ Passed**Advice** Front Items removed from driver's view prior to test**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #13** 2020-03-06 09:29**MOT test number** 747131277988**Result** ✗ Failed**Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Front Items removed from driver's view prior to test**Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #12** 2019-02-14 15:03**MOT test number** 321178983192**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement both bushes (5.3.4 (a) (i))

**MOT #11** 2019-02-14 11:40**MOT test number** 341041065758**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement both bushes (5.3.4 (a) (i))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt clip (6.1.7 (g) (ii))**MOT #10** 2017-11-16 14:55**MOT test number** 210087407609**Result** ✓ Passed**MOT #9** 2017-11-16 10:54**MOT test number** 929900177314**Result** ✗ Failed**Pass with rectification** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #8** 2016-11-14 14:00**MOT test number** 846867166686**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit inside edge (4.1.E.1)

**MOT #7** 2016-11-04 11:38**MOT test number** 251054658697**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**Advice** Offside Front Tyre worn close to the legal limit inside edge (4.1.E.1)**Pass with rectification** Offside Headlamp aim too low (1.8)**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #6** 2015-10-03 08:18**MOT test number** 300294104933**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** UNDERTRAYS**MOT #5** 2015-09-26 09:59**MOT test number** 220159281127**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** UNDERTRAYS**Fail** Front Tyre tread depth below requirements of 1.6mm BOTH (4.1.E.1)**Advice** REAR SEATS MISSING**MOT #4** 2014-09-16 15:34**MOT test number** 577919354231**Result** ✓ Passed



MOT #3	2013-09-10 16:36
MOT test number	867463353229
Result	✓ Passed
MOT #2	2012-09-04 18:23
MOT test number	468008142223
Result	✓ Passed
MOT #1	2011-09-02 09:10
MOT test number	396845841433
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
7 April 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	7 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>YX580YH</b>
Plate since	2019-09-28
Current registration	<b>YX580YH</b>
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-09-13
Last registration	2024-03-19
Complete history	<a href="#">See info</a>



Registration #1	2008-09-13	9 mi
Registration #2	2011-09-02	21.621 mi
Registration #3	2012-09-04	27.307 mi
Registration #4	2013-09-10	32.390 mi
Registration #5	2014-09-16	36.856 mi
Registration #6	2015-09-26	52.762 mi
Registration #7	2015-10-03	53.107 mi
Registration #8	2016-11-04	69.821 mi
Registration #9	2016-11-14	70.279 mi
Registration #10	2017-11-16	86.014 mi
Registration #11	2017-11-16	86.018 mi
Registration #12	2018-03-20	91.377 mi
Registration #13	2018-03-20	91.377 mi
Registration #14	2018-03-20	91.377 mi
Registration #15	2018-03-20	91.377 mi
Registration #16	2018-03-20	91.377 mi
Registration #17	2018-03-20	91.377 mi
Registration #18	2018-03-20	91.377 mi
Registration #19	2018-03-20	91.377 mi
Registration #20	2018-03-20	91.377 mi
Registration #21	2018-03-20	91.377 mi
Registration #22	2018-03-20	91.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1829 mm
Height	1700 mm
Length	4585 mm
Wheel base	2728 mm
Kerb weight	1539 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBAJ3070542