



0E11HV1

report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) COOPER
Colour	Green
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 3

Date	2023-03-22
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 2

Date	2022-11-04
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-02-02
Pictures	4
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-10-18
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	22
Total items failed	6

MOT #13	2023-10-11 15:34
MOT test number	877598678232
Result	✓ Passed
Next expiry date	2024-10-18

MOT #12	2023-10-11 14:27
MOT test number	790902187595
Result	✗ Failed
Fail	Front Service brake excessively fluctuating (1.2.1 (e))
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #11	2022-10-19 11:18
MOT test number	708080362417
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Exhaust has a minor leak of exhaust gases Down pipe (6.1.2 (a))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #10**

2022-10-05 11:09

MOT test number

240362328925

Result

✗ Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing side wall (5.2.3 (d) (ii))**Fail** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MOT #9**

2021-09-30 13:09

MOT test number

548665568513

Result

✓ Passed

MOT #8

2020-10-02 13:11

MOT test number

945493912770

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7**

2019-09-06 08:55

MOT test number

156661068342

Result

✓ Passed

Advice

Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement 'D' bush (5.3.4 (a) (i))

Advice

Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice

Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement 'D' bush (5.3.4 (a) (i))

Advice

Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #6

2018-09-10 08:55

MOT test number

431694755981

Result

✓ Passed

Advice

Front Exhaust has a minor leak of exhaust gases flexi pipe (6.1.2 (a))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5

2017-10-06 11:04

MOT test number

900826602805

Result

✓ Passed

MOT #4

2016-09-30 09:45

MOT test number

108725623631

Result

✓ Passed

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2015-09-17 15:23
MOT test number	704256671491
Result	✓ Passed

MOT #2	2015-06-10 10:21
MOT test number	228501965178
Result	✓ Passed
<div><div>Notice</div>Under-trays fitted obscuring some underside components</div> <div><div>Advice</div>Front Brake pad(s) wearing thin (3.5.1g)</div> <div><div>Notice</div>Engine covers fitted obscuring some components in the engine bay</div>	

MOT #1	2014-06-09 12:26
MOT test number	347880464149
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
18 October 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	18 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-06-30
Last registration	2023-10-11
Complete history	See info



Registration #1	2011-06-30	24 mi
Registration #2	2014-06-09	25.501 mi
Registration #3	2015-06-10	36.057 mi
Registration #4	2015-09-17	37.980 mi
Registration #5	2016-09-30	49.375 mi
Registration #6	2017-10-06	59.536 mi
Registration #7	2018-09-10	69.282 mi
Registration #8	2019-09-06	79.794 mi
Registration #9	2020-10-02	88.438 mi
Registration #10	2020-10-02	88.438 mi
Registration #11	2020-10-02	88.438 mi
Registration #12	2020-10-02	88.438 mi
Registration #13	2020-10-02	88.438 mi
Registration #14	2020-10-02	88.438 mi
Registration #15	2020-10-02	88.438 mi
Registration #16	2020-10-02	88.438 mi
Registration #17	2020-10-02	88.438 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1265 kg
Max. allowed weight	1735 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	A023I929