



report date: 2024-03-29

General information

Make	KIA
Model	CEED 2
Colour	Red
Year of manufacture	2010
Top speed	119 mph
0 - 60 mph	10.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	124 BHP
Max. torque	154 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 2



Date	2021-01-31
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	12
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2024-07-10
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	45
Total items failed	19

MOT #19	2023-07-11 08:38
MOT test number	497096180204
Result	✓ Passed
Next expiry date	2024-07-10
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #18**

2023-07-05 15:12

MOT test number

473307335478

Result

✗ Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

Fail Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #17

2022-07-01 09:35

MOT test number

482647929793

Result

✓ Passed

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bushes (5.3.4 (a) (i))

Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement both trailing arm bushes (5.3.4 (a) (i))

Advice Parking brake lever defective but can be satisfactorily operated advise adjustment (1.1.6 (d))

**MOT #16**

2022-07-01 09:35

MOT test number

584057046803

Result

✗ Failed

Advice Parking brake lever defective but can be satisfactorily operated advise adjustment (1.1.6 (d))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bushes (5.3.4 (a) (i))**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both trailing arm bushes (5.3.4 (a) (i))**MOT #15**

2021-07-07 15:42

MOT test number

845028416781

Result

✓ Passed

MOT #14

2021-07-06 11:38

MOT test number

938251034887

Result

✗ Failed

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**MOT #13**

2020-07-27 11:21

MOT test number

650391118448

Result

✓ Passed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened inner face corroding (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn rear axle front bushes perishing (5.1.2 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #12**

2020-07-27 09:16

MOT test number

832940626097

Result

✗ Failed

Fail Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened inner face corroding (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn rear axle front bushes perishing (5.1.2 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #11**

2019-07-30 13:31

MOT test number

931489658058

Result

✓ Passed

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2019-07-30 09:54

MOT test number

822241662751

Result

✗ Failed

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #9**

2018-08-14 09:23

MOT test number

353866431881

Result

✓ Passed

**MOT #8**

2018-08-07 10:59

MOT test number

581345513731

Result**✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn wishbone (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))**Fail** Offside Front Inner Drive shaft joint excessively worn (6.1.7 (c) (i))**MOT #7**

2017-10-17 07:46

MOT test number

265237297452

Result**✓ Passed****Advice** Nearside rear tyre low on inner edge & stepped**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #6**

2017-10-09 10:08

MOT test number

541901514671

Result**✗ Failed**

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Fail** Nearside front brake excessively fluctuating (3.7.B.3)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside rear tyre low on inner edge & stepped
- Advice** Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #5

2016-07-23 08:05

MOT test number

678530260852

Result**✓ Passed****MOT #4**

2016-07-23 08:05

MOT test number

461605964906

Result**✗ Failed**

- Pass with rectification** Nearside Stop lamp not working (1.2.1b)
- Pass with rectification** Offside Stop lamp not working (1.2.1b)



MOT #3	2015-07-28 12:05
MOT test number	595919305273
Result	✓ Passed

MOT #2	2014-09-27 15:47
MOT test number	367720574441
Result	✓ Passed

MOT #1	2013-09-18 09:42
MOT test number	115541863246
Result	✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

X

Untaxed

Tax expired:
30 October 2023

✓

MOT

Expires:
10 July 2024

Tax status	Expired at 30 October 2023
Days left	183 days too late
MOT expiry date	10 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	LD60RYR
Plate since	2019-03-29
Current registration	LD60RYR
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2010-09-29
Last registration	2023-07-11
Complete history	See info



Registration #1	2010-09-29	21 mi
Registration #2	2013-09-18	23.670 mi
Registration #3	2014-09-27	34.848 mi
Registration #4	2015-07-28	35.251 mi
Registration #5	2016-07-23	44.139 mi
Registration #6	2016-07-23	44.139 mi
Registration #7	2017-10-09	53.377 mi
Registration #8	2017-10-17	53.427 mi
Registration #9	2018-08-07	58.358 mi
Registration #10	2018-08-14	58.389 mi
Registration #11	2019-07-30	61.216 mi
Registration #12	2019-07-30	61.216 mi
Registration #13	2019-07-30	61.216 mi
Registration #14	2019-07-30	61.216 mi
Registration #15	2019-07-30	61.216 mi
Registration #16	2019-07-30	61.216 mi
Registration #17	2019-07-30	61.216 mi
Registration #18	2019-07-30	61.216 mi
Registration #19	2019-07-30	61.216 mi
Registration #20	2019-07-30	61.216 mi
Registration #21	2019-07-30	61.216 mi
Registration #22	2019-07-30	61.216 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1790 mm
Height	1480 mm
Length	4235 mm
Wheel base	2650 mm
Kerb weight	1263 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FC9Z130366