





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	ML ML250 BLUETEC AMG SPORT
Colour	Grey
Year of manufacture	2014
Top speed	130 mph
0 - 100 km/h	9.0 seconds
0 - 60 mph	9.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	150 kW / 204 HP / 204 BHP
Max. torque	500 Nm at 1.800 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.8 mpg
CO2 emission	163 g/km
CO2 label	G



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2022-01-11

Pictures 51

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-29
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	17
Total items failed	1

MOT #12	2023-11-20 10:26
MOT test number	351147650253
Result	✓ Passed
Next expiry date	2024-11-29

MOT #11	2023-11-16 10:11
MOT test number	559145199505
Result	X Failed
MAJOR Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
DANGEROUS Nearside Front Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))	
Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
DANGEROUS Offside Front Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))	

MOT #10	2022-11-22 16:30
MOT test number	491833155458
Result	✓ Passed

CarCheck.co.uk page 3/12



Result

KV64RZB

report date: 2024-03-29

× Failed

MOT test number

Result

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8 2021-11-30 17:07

MOT test number 377389840746

Result ✓ Passed

 MOT #7
 2021-11-30 12:50

 MOT test number
 748650024042

DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #6 2020-11-26 07:11
MOT test number 371664119518

MOT #5 2020-11-04 16:06

MOT test number 149573462423

Result X Failed

MAJOR Windscreen washer not working (3.5 (a))

MAJOR Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 4/12



KV64RZB

report date: 2024-03-29

MOT #4

MOT test number

544900713061

Result

Advice Offside Front Nail in tyre

MOT #3

MOT test number

Result

Pass with rectification

Offside Rear Lower Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Offside Front Nail in tyre

 MOT #2
 2018-10-25 14:27

 MOT test number
 185859666420

 Result
 ✓ Passed

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit ON THE LIMIT (4.1.E.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Tyre worn close to the legal limit ON THE LIMIT (4.1.E.1)

Advice Oil leak

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	29 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How material MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. report here .	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NK UK
Plate since	
Current registration	NE UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combont info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-09-12
Last registration	2023-11-20
Complete history	See info



Registration #1	2014-09-12	6 mi
Registration #2	2017-09-11	47.521 mi
Registration #3	2018-10-25	60.605 mi
Registration #4	2019-10-17	76.239 mi
Registration #5	2019-10-17	76.239 mi
Registration #6	2020-11-04	87.637 mi
Registration #7	2020-11-26	87.729 mi
Registration #8		11.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		11.177 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
0567	
60569	
iew the complete MERCEDES-BENZ factory list for this	More info >

				_			
ונו	men:	CIOT	nc -	λ.	WAI	α	ht.
וט	пеп	STUI	13	CX.	$VV \subset I$	ш	TTU.

Width	1998 mm
Height	1796 mm
Length	4804 mm
Wheel base	2915 mm
Kerb weight	2150 kg
Max. allowed weight	2950 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	65196032261542

CarCheck.co.uk page 12/12