




report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | LAND ROVER |
| Model | FREELANDER TD4 XS |
| Colour | Grey |
| Year of manufacture | 2011 |
| Top speed | 112 mph |
| 0 - 100 km/h | 11.7 seconds |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------------|
| Power | 110 kW / 150 HP / 150 BHP |
| Max. torque | 420 Nm at 1.750 rpm |
| Engine capacity | 2.179 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 38.2 mpg |
| Consumption extra urban | 50.4 mpg |
| Consumption combined | 45.6 mpg |
| CO2 emission | 165 g/km |
| CO2 label | G |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-18 |
| Pictures | 21 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-04-08 |
| MOT pass rate | 73 % |
| MOT passed | 11 |
| Failed MOT tests | 4 |
| Total advice items | 66 |
| Total items failed | 1 |

| | |
|------------------|--|
| MOT #15 | 2024-04-09 16:16 |
| MOT test number | 540022859520 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-08 |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|---|
| MOT #14 | 2024-03-29 10:19 |
| MOT test number | 192596471532 |
| Result | ✗ Failed |
| Advice | Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear mount (5.3.4 (a) (i)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| MAJOR | Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) |
| MAJOR | Offside Front Suspension arm pin or bush excessively worn rear mount (5.3.4 (a) (i)) |
| Advice | Items removed from driver's view prior to test |
| MAJOR | Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) |

**MOT #13**

2023-04-01 15:38

MOT test number

949970406750

Result

✓ Passed

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Items removed from driver's view prior to test

Advice

Power steering close to minimum mark (2.1.5 (b) (i))

MOT #12

2023-04-01 14:06

MOT test number

941884461658

Result

✗ Failed

MAJOR

Offside Front Direction indicator incorrect colour (4.4.3 (a))

MAJOR

Nearside Front Direction indicator incorrect colour (4.4.3 (a))

Advice

Power steering close to minimum mark (2.1.5 (b) (i))

Pass with rectification

Nearside Headlamp aim too high (4.1.2 (a))

Advice

Items removed from driver's view prior to test

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11

2022-02-17 15:00

MOT test number

343149517786

Result

✓ Passed



MOT #102021-02-22 13:20

MOT test number660731931242

Result

✓ Passed

- Advice

Offside Front All direction indicators slightly discoloured (4.4.3 (a))
- Advice

Offside Rear All direction indicators slightly discoloured (4.4.3 (a))
- Advice

Nearside Front All direction indicators slightly discoloured (4.4.3 (a))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice

Front front bonnet struts weak
- Advice

Nearside Rear All direction indicators slightly discoloured (4.4.3 (a))
- Advice

Hydraulic leak, but not excessive at power steering pump/pipe (8.4.1 (a) (i))

**MOT #9**

2021-02-19 12:19

MOT test number

405641374464

Result**✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Front front bonnet struts weak**Advice** Offside Front All direction indicators slightly discoloured (4.4.3 (a))**Advice** Offside Rear All direction indicators slightly discoloured (4.4.3 (a))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**DANGEROUS** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front All direction indicators slightly discoloured (4.4.3 (a))**Advice** Nearside Rear All direction indicators slightly discoloured (4.4.3 (a))**Advice** Hydraulic leak, but not excessive at power steering pump/pipe (8.4.1 (a) (i))



MOT #82020-02-14 15:47

MOT test number584694263047

| Result | | ✓ Passed |
|--------|---|----------|
| Advice | Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) | |
| Advice | Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Nearside Rear unable to fully inspect wheel bearing as brake binding | |
| Advice | Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

**MOT #7** 2020-02-13 12:30**MOT test number** 506538500015**Result** ✗ Failed**Advice** Nearside Rear unable to fully inspect wheel bearing as brake binding**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**DANGEROUS** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2019-02-12 11:16**MOT test number** 363365932101**Result** ✓ Passed**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Front Power steering fluid level below minimum (2.1.5 (b) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #5** 2018-02-09 15:55**MOT test number** 672141656099**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre misshaped.**MOT #4** 2017-02-13 10:40**MOT test number** 306094474102**Result** ✓ Passed**MOT #3** 2016-02-29 14:01**MOT test number** 353907280878**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2015-03-04 17:03**MOT test number** 427953365077**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2014-03-03 10:27**MOT test number** 975962464031**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
8 April 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 279 |
| MOT expiry date | 8 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 15,200 |
| Auction value | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-29 |
| Current registration | ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.


| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2011-03-28 |
| Last registration | 2024-04-09 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2011-03-28 | 14 mi |
| Registration #2 | 2014-03-03 | 23.139 mi |
| Registration #3 | 2015-03-04 | 39.601 mi |
| Registration #4 | 2016-02-29 | 59.153 mi |
| Registration #5 | 2017-02-13 | 79.094 mi |
| Registration #6 | 2018-02-09 | 97.795 mi |
| Registration #7 | 2019-02-12 | 116.300 mi |
| Registration #8 | 2020-02-13 | 135.804 mi |
| Registration #9 | 2020-02-14 | 135.804 mi |
| Registration #10 | 2020-02-14 | 135.804 mi |
| Registration #11 | 2020-02-14 | 135.804 mi |
| Registration #12 | 2020-02-14 | 135.804 mi |
| Registration #13 | 2020-02-14 | 135.804 mi |
| Registration #14 | 2020-02-14 | 135.804 mi |
| Registration #15 | 2020-02-14 | 135.804 mi |
| Registration #16 | 2020-02-14 | 135.804 mi |
| Registration #17 | 2020-02-14 | 135.804 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Video | see crash video |



Dimensions & weight

| | |
|-------------|---------|
| Width | 2180 mm |
| Height | 1740 mm |
| Length | 4500 mm |
| Wheel base | 2660 mm |
| Kerb weight | 1770 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 68 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | DZ794013534224DT |