





General information

| Make | MINI |
|---------------------|------------------|
| Model | MINI (R60) ONE D |
| Colour | White |
| Year of manufacture | 2011 |
| Top speed | 106 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 90 BHP |
|-------------------------|---------------------|
| Max. torque | 215 Nm at 1.750 rpm |
| Engine capacity | 1.600 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 60.1 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 115 g/km |
| CO2 label | С |







Internet history

Entry 1

Date Pictures 2022-07-03

12

Listing price

View report









source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-07-13 |
|--------------------|------------|
| MOT pass rate | 77 % |
| MOT passed | 10 |
| Failed MOT tests | 3 |
| Total advice items | 15 |
| Total items failed | 6 |

| MOT #13 | 2 | 023-07-11 12:32 |
|----------------------|---|-----------------|
| MOT test | number | 892742742513 |
| Result | | 🗸 Passed |
| Next expi | ry date | 2024-07-13 |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Clutch pedal heavy & biting point high | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing 205/55R17V (5.2.3 (d) (ii) |) |
| Advice | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice inoperativ | Tyre pressure lamp on ?- Tyre pressure monitoring system malfunctioning or obvio e | usly |

| MOT #12 | 2023-07-11 12:32 | |
|---|------------------|--|
| MOT test number | 243636179654 | |
| Result | 🗙 Failed | |
| Advice Clutch pedal heavy & biting point high | | |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing 205/55R17V (5.2.3 (d) (ii)) | | |
| Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | | |
| Advice Tyre pressure lamp on ?- Tyre pressure monitoring system malfunctioning or obviously inoperative | | |
| Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | | |
| Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii)) | | |





| MOT #11 | 2022-07-14 10:57 |
|---|------------------|
| MOT test number | 971773569826 |
| Result | ✓ Passed |
| | |
| MOT #10 | 2022-07-06 09:51 |
| MOT test number | 214378650280 |
| Result | 🗙 Failed |
| Fail Nearside Rear Brake cable damaged (1.1.15 (a)) | |
| Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) | |
| | |
| MOT #9 | 2021-09-25 09:50 |
| MOT test number | 610268870758 |

MOT test number619268879758Result✓ Passed

| MOT #8 | 3 | 2021-09-18 10:47 |
|--------|--|------------------|
| MOT te | st number | 583578968067 |
| Result | | 🗙 Failed |
| Fail | Offside Rear Brake cable damaged snapped (1.1.15 (a)) | |
| Fail | Offside Rear Parking brake inoperative on one side (1.4.1 (a)) | |
| Fail | Parking brake efficiency below requirements (1.4.2 (a) (i)) | |

| MOT #7 | 2020-09-12 09:21 |
|-----------------|------------------|
| MOT test number | 208280089845 |
| Result | ✓ Passed |





| MOT #6 | | 2019-10-03 15:58 |
|--------------|---|------------------|
| MOT test num | ber | 657075525615 |
| Result | | ✓ Passed |
| Minor Wind | dscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |
| Advice Offs | side Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Nea | arside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Offs | side Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #5 | 2018-09-11 09:03 |
|-----------------|------------------|
| MOT test number | 499724488557 |
| Result | ✓ Passed |

| MOT #4 | 2017-09-30 08:57 |
|-----------------|------------------|
| MOT test number | 685057569164 |
| Result | ✓ Passed |

| MOT #3 | 2016-10-03 09:21 |
|-----------------|------------------|
| MOT test number | 112959573756 |
| Result | ✓ Passed |

| MOT #2 | 2015-10-06 10:13 |
|---|------------------|
| MOT test number | 925453870302 |
| Result | ✓ Passed |
| Advice Front Brake pad(s) wearing thin (3.5.1g) | |

| MOT #1 | 2014-09-24 10:25 |
|-----------------|------------------|
| MOT test number | 266187064286 |
| Result | ✓ Passed |



Tax & MOT check

| Tax due: 1 January 2025 | ✓ Taxed | Expires: 13 July 2024 | ✓ МОТ |
|-----------------------------------|------------|---------------------------------|-----------------------|
| Tax status | | | Valid until 1 January |
| Days left | | | 247 |
| MOT expiry date | | | 13 July 2024 |
| Full MOT history | | | See MOT history |
| Tax calculation | | | |
| Vehicle class | | 49 | |

| Vehicle class | 49 |
|---|----------------|
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| Date | |
| Date | OLE |
| Category | E.S. |
| Туре | |

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|---|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this MINI had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | |





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2011-09-30 |
| Last registration | 2023-07-11 |
| Complete history | See info |



| Registration #1 | 2011-09-30 | 24 mi |
|------------------|------------|------------|
| Registration #2 | 2014-09-24 | 20.740 mi |
| Registration #3 | 2015-10-06 | 25.413 mi |
| Registration #4 | 2016-10-03 | 32.974 mi |
| Registration #5 | 2017-09-30 | 46.586 mi |
| Registration #6 | 2018-09-11 | 61.892 mi |
| Registration #7 | 2019-10-03 | 69.023 mi |
| Registration #8 | 2020-09-12 | 74.825 mi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 11.777 mi |
| Registration #14 | | 11.777 esi |
| Registration #15 | | 11.777 mi |





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|---|--------------------------|
| Width | 1789 mm |
| Height | 1561 mm |
| Length | 4097 mm |
| Wheel base | 2595 mm |
| Max. allowed weight | 1820 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 47 |
| | 47 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |

Engine number

73317833