



report date: 2024-03-29

General information

Make	MINI
Model	ONE D COOPER D
Colour	Blue
Year of manufacture	2011
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2025-02-18
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	19
Total items failed	7

## MOT #12 2024-02-19 13:30

MOT test number 769221187902

Result ✓ Passed

Next expiry date 2025-02-18

**Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Tyre pressure warning lamp on

## MOT #11 2022-07-13 10:28

MOT test number 959846420342

Result ✓ Passed

## MOT #10 2022-07-13 08:18

MOT test number 477150383314

Result ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge and cracking (5.2.3 (e))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #9** 2021-06-25 15:39**MOT test number** 297457969730**Result** ✓ Passed**MOT #8** 2019-12-13 17:04**MOT test number** 865278507710**Result** ✓ Passed**Advice** Rear Brake disc worn, but not excessively both ns and os (1.1.14 (a) (i))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords on outer sidewall (5.2.3 (d) (i))**MOT #7** 2019-12-05 12:17**MOT test number** 782339890098**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure on inner sidewall (5.2.3 (d) (ii))**Advice** Rear Brake disc worn, but not excessively both ns and os (1.1.14 (a) (i))**Advice** Service warning on dash**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords on outer sidewall (5.2.3 (d) (i))**Fail** Headlamp levelling device inoperative warning also displayed on dash (4.1.5 (a))**MOT #6** 2018-11-16 13:40**MOT test number** 405239933884**Result** ✓ Passed**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear of subframe (5.3.4 (a) (i))

**MOT #5** 2018-11-16 13:40**MOT test number** 375575411509**Result** ✗ Failed

**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear of subframe (5.3.4 (a) (i))

**MOT #4** 2017-11-10 12:00**MOT test number** 397123556797**Result** ✓ Passed

**Advice** Tyre pressure monitoring system warning lamp does not illuminate (4.1.D.4)

**MOT #3** 2016-11-29 12:19**MOT test number** 742160627269**Result** ✓ Passed**MOT #2** 2015-07-24 12:06**MOT test number** 355675805440**Result** ✓ Passed

**Notice** Advise replacment of front tyres

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2014-05-30 12:21
MOT test number	745870354139
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
18 February 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	18 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-06-14
Last registration	2024-02-19
Complete history	<a href="#">See info</a>



Registration #1	2011-06-14	13 mi
Registration #2	2014-05-30	41.440 mi
Registration #3	2015-07-24	54.819 mi
Registration #4	2016-11-29	75.233 mi
Registration #5	2017-11-10	87.640 mi
Registration #6	2018-11-16	90.886 mi
Registration #7	2018-11-16	90.886 mi
Registration #8	2019-05-29	95.277 mi
Registration #9	2019-05-29	95.277 mi
Registration #10	2019-05-29	95.277 mi
Registration #11	2019-05-29	95.277 mi
Registration #12	2019-05-29	95.277 mi
Registration #13	2019-05-29	95.277 mi
Registration #14	2019-05-29	95.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	70757967