



General information

Make	FIAT
Model	GRANDE PUNTO SOUND
Colour	Blue
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-09-06
Pictures	7
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-01
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	23
Total items failed	19

MOT #19	2023-06-02 10:46
MOT test number	965672833867
Result	✓ Passed
Next expiry date	2024-06-01
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18	2023-06-01 13:10
MOT test number	238602499278
Result	✗ Failed
Fail	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Emissions unable to be completed (8.2.1.2 (d))
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MOT #17**

2022-08-08 09:17

**MOT test number**

213543270313

**Result**

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #16**

2022-08-08 09:17

**MOT test number**

734451451716

**Result**

✗ Failed

**Pass with rectification** Nearside Front Direction indicator incorrect colour (4.4.3 (a))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #15**

2021-08-11 08:28

**MOT test number**

163579594029

**Result**

✓ Passed

**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))

**Advice** Items removed from driver's view prior to test

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))

**Advice** Front Inner Suspension arm pin or bush worn but not resulting in excessive movement both arms (5.3.4 (a) (i))

**MOT #14** 2021-08-10 12:28**MOT test number** 388189976476**Result** ✗ Failed

- Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Front Inner Suspension arm pin or bush worn but not resulting in excessive movement both arms (5.3.4 (a) (i))

**MOT #13** 2020-08-04 14:24**MOT test number** 700609954352**Result** ✓ Passed**MOT #12** 2020-08-04 10:00**MOT test number** 638866662652**Result** ✗ Failed

- Fail** Offside Rear Shock absorbers damaged to the extent that it does not function unstable due to excessive movement (5.3.2 (b))
- Fail** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
- Fail** Nearside Rear Shock absorbers damaged to the extent that it does not function unstable due to rear end excessive movement (5.3.2 (b))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))

**MOT #11** 2019-08-08 10:46**MOT test number** 729855919614**Result** ✓ Passed**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**MOT #10** 2018-07-25 16:01**MOT test number** 263662337723**Result** ✓ Passed**MOT #9** 2018-07-24 11:03**MOT test number** 774832038280**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2017-08-04 15:40**MOT test number** 440658976889**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2017-08-04 15:40**MOT test number** 843715861036**Result** ✗ Failed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Pass with rectification** Fuel cap/sealing device sealing washer missing (7.2.4c)

**MOT #6** 2016-09-21 12:53**MOT test number** 695583150523**Result** ✓ Passed**MOT #5** 2016-09-21 12:53**MOT test number** 631463437177**Result** ✗ Failed**Pass with rectification** Rear fog lamp not working (1.3.2b)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2015-09-23 16:08**MOT test number** 703119926709**Result** ✓ Passed**MOT #3** 2015-09-23 14:43**MOT test number** 211480803692**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (1.8)**Fail** Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' sat nav (8.3.1b)**Fail** Offside Rear fog lamp not working (1.3.2b)**MOT #2** 2014-09-11 17:32**MOT test number** 725544654277**Result** ✓ Passed**MOT #1** 2013-09-25 11:37**MOT test number** 519898063203**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

Tax due:  
1 July 2024

✓  
**MOT**

Expires:  
1 June 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	1 June 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-10-28
Last registration	2023-06-02
Complete history	<a href="#">See info</a>



Registration #1	2010-10-28	17 mi
Registration #2	2013-09-25	14.419 mi
Registration #3	2014-09-11	18.879 mi
Registration #4	2015-09-23	25.062 mi
Registration #5	2015-09-23	25.063 mi
Registration #6	2016-09-21	32.826 mi
Registration #7	2016-09-21	32.826 mi
Registration #8	2017-08-04	36.616 mi
Registration #9	2017-08-04	36.616 mi
Registration #10	2018-07-24	42.543 mi
Registration #11	2018-07-25	42.543 mi
Registration #12	2019-06-20	50.377 mi
Registration #13	2019-06-20	50.377 mi
Registration #14	2019-06-20	50.377 mi
Registration #15	2019-06-20	50.377 mi
Registration #16	2019-06-20	50.377 mi
Registration #17	2019-06-20	50.377 mi
Registration #18	2019-06-20	50.377 mi
Registration #19	2019-06-20	50.377 mi
Registration #20	2019-06-20	50.377 mi
Registration #21	2019-06-20	50.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	9632561
---------------	---------