



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA HDI DESIRE PICASSO E4
Colour	Silver
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN



Internet history



Entry 2

Date	2021-12-29
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-07-30
Pictures	24
Listing price	View report



source: cargurus.co.uk



MOT history

MOT #17 2022-07-11 15:11**MOT test number** 670784205278**Result** ✓ Passed**Next expiry date** 2023-07-27

Advice Suspension rod attachment bracket/mounting corroded but its strength is not seriously reduced
Torsion bars are corroded. (5.3.3 (b) (i))

MOT #16 2022-07-04 10:20**MOT test number** 100496320326**Result** ✗ Failed

Advice Suspension rod attachment bracket/mounting corroded but its strength is not seriously reduced
Torsion bars are corroded. (5.3.3 (b) (i))

MAJOR Nearside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced
outer sill panel excessive corrosion. (7.1.1 (a) (i))

MOT #15 2021-07-28 16:08**MOT test number** 914770282237**Result** ✓ Passed

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #14**

2021-07-08 13:23

MOT test number

823251262485

Result**✗ Failed**

MAJOR Nearside Front Outer Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Sill (6.1.1 (c) (i))

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Detached (6.1.7 (g) (ii))

Advice Oil leak

Advice Centre stop light is not working

MAJOR Offside Outer Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Sill (6.1.1 (c) (i))

MAJOR Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Split (6.1.7 (g) (ii))

MAJOR Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt Boot split (5.3.4 (b) (ii))

Advice Rear axle corroded

MOT #13

2020-07-14 13:45

MOT test number

224489853757

Result**✓ Passed**

Advice Rear Tyre slightly damaged/cracking or perishing both tyres cracking in tread (5.2.3 (d) (ii))

Advice Nearside Front Nail in tyre

Advice Nearside Front both CV gaiters weeping

**MOT #12**

2020-07-13 14:14

MOT test number

114754444466

Result**✗ Failed****MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Minor** Nearside Front Tyre obviously under inflated (5.2.3 (I))**Advice** Nearside Front both CV gaiters weeping**Advice** Rear Tyre slightly damaged/cracking or perishing both tyres cracking in tread (5.2.3 (d) (ii))**Advice** Nearside Front Nail in tyre**MOT #11**

2019-03-08 15:39

MOT test number

932279833217

Result**✓ Passed****Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Part of induction system missing**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Oil leak, but not excessive engine/gearbox (8.4.1 (a) (i))**Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive axle mounting points (5.3.6 (a) (i))**Advice** Undersheild fitted**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Front fog light tell tail not illuminating

**MOT #10**

2019-03-08 11:25

MOT test number

806282446895

Result**✗ Failed****DANGEROUS** Nearside Rear Valve stem seriously damaged (5.2.3 (j))**Advice** Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Front fog light tell tail not illuminating**Advice** Part of induction system missing**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive axle mounting points (5.3.6 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Undersheild fitted**Advice** Oil leak, but not excessive engine/gearbox (8.4.1 (a) (i))**MOT #9**

2018-03-05 16:06

MOT test number

948805388632

Result**✓ Passed****Advice** Offside Front tyre worn on inner edge**Advice** Nearside Front tyre damaged on outer side wall**Advice** Under tray fitted

**MOT #8** 2018-03-05 09:04**MOT test number** 156032564123**Result** ✗ Failed**Advice** Nearside Front tyre damaged on outer side wall**Advice** Coolant low**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Offside Front tyre worn on inner edge**Advice** Under tray fitted**MOT #7** 2017-03-21 08:50**MOT test number** 808936661094**Result** ✓ Passed**MOT #6** 2017-03-16 15:33**MOT test number** 633626436791**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2016-03-03 12:35**MOT test number** 182715562342**Result** ✓ Passed**MOT #4** 2015-02-19 14:57**MOT test number** 376550155063**Result** ✓ Passed

**MOT #3** 2014-02-19 16:22**MOT test number** 309300854064**Result** ✓ Passed**Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**MOT #2** 2013-02-11 12:15**MOT test number** 908612443043**Result** ✓ Passed**Notice** Rear exhaust box supporting strap is corroded**Notice** N/s front tyre outer wall is perished**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-03-07 15:28**MOT test number** 819547662091**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-11
Last registration	2022-07-11
Complete history	See info



Registration #1	2009-03-11	25 mi
Registration #2	2012-03-07	34.008 mi
Registration #3	2013-02-11	43.610 mi
Registration #4	2014-02-19	56.496 mi
Registration #5	2015-02-19	66.196 mi
Registration #6	2016-03-03	78.323 mi
Registration #7	2017-03-16	86.971 mi
Registration #8	2017-03-21	86.973 mi
Registration #9	2018-03-05	95.235 mi
Registration #10	2018-03-05	95.237 mi
Registration #11	2019-03-05	95.237 mi
Registration #12	2019-03-05	95.237 mi
Registration #13	2019-03-05	95.237 mi
Registration #14	2019-03-05	95.237 mi
Registration #15	2019-03-05	95.237 mi
Registration #16	2019-03-05	95.237 mi
Registration #17	2019-03-05	95.237 mi
Registration #18	2019-03-05	95.237 mi
Registration #19	2019-03-05	95.237 mi
Registration #20	2019-03-05	95.237 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBAW3025790