



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 CDTI CREWVAN
Colour	White
Year of manufacture	2008
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	170 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-30
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-02
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	53
Total items failed	10

MOT #162023-07-25 13:33

MOT test number575800465219

Result✓ Passed

Next expiry date2024-08-02

- AdviceNearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- AdviceOffside Front Play in steering rack inner joint(s)
- AdviceExhaust rear silencer deteriorated
- AdviceNearside Front Play in steering rack inner joint(s)
- AdviceExhaust has a minor leak of exhaust gases Rear silencer (6.1.2 (a))
- AdviceOffside Front Shock absorbers has light misting of oil (5.3.2 (b))
- AdviceWarning light on dashboard
- MinorOffside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- AdviceOffside Rear Nail in tyre



MOT #15

2023-07-25 10:11

MOT test number

286428866372

Result		✗ Failed
Advice	Exhaust rear silencer deteriorated	
Advice	Offside Rear Nail in tyre	
Advice	Exhaust has a minor leak of exhaust gases Rear silencer (6.1.2 (a))	
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice	Offside Front Play in steering rack inner joint(s)	
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Warning light on dashboard	
Advice	Nearside Front Play in steering rack inner joint(s)	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))	



MOT #14

2022-07-26 14:40

MOT test number

493710491246

Result		✓ Passed
Advice	Warning light on dashboard	
Advice	Nearside Front Play in steering rack inner joint(s)	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Front Play in steering rack inner joint(s)	
Advice	Exhaust has a minor leak of exhaust gases Rear silencer (6.1.2 (a))	
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Cracking/Perished (5.2.3 (d) (ii))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

**MOT #13**

2022-07-26 11:09

MOT test number

434358611885

Result**✗ Failed****Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Cracking/Perished (5.2.3 (d) (ii))**Fail** Brake performance not tested Due to leak (1.2.1 (g))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Warning light on dashboard**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Exhaust has a minor leak of exhaust gases Rear silencer (6.1.2 (a))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Play in steering rack inner joint(s)

**MOT #12**

2021-08-03 09:39

MOT test number

190897048684

Result

✓ Passed

- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Exhaust has a minor leak of exhaust gases rear box (6.1.2 (a))
- Advice** Front Shock absorbers light misting of oil or has limited damping effect both (5.3.2 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11

2020-07-27 08:20

MOT test number

539520231675

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Exhaust has a minor leak of exhaust gases on silencer (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

2019-07-04 09:11

MOT test number

894479676435

Result

✓ Passed

MOT #9

2018-06-12 11:28

MOT test number

517445787981

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8

2017-06-06 14:04

MOT test number

491508857810

Result

✓ Passed

**MOT #7** 2017-06-05 19:55**MOT test number** 696547703995**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Offside Front Tyre worn close to the legal limit Tread depth on 2mm (4.1.E.1)**MOT #6** 2016-07-01 21:36**MOT test number** 947139460337**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2015-09-02 10:31**MOT test number** 743205662216**Result** ✓ Passed**MOT #4** 2014-08-29 12:22**MOT test number** 745761044259**Result** ✓ Passed**MOT #3** 2013-08-15 21:19**MOT test number** 809767723298**Result** ✓ Passed



MOT #2	2012-09-06 15:00
MOT test number	288740352225
Result	✓ Passed

MOT #1	2011-09-08 09:41
MOT test number	436561251201
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
2 August 2024

Tax status	Valid until 1 February
-------------------	------------------------

Days left	277
------------------	-----

MOT expiry date	2 August 2024
------------------------	---------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 WV58VZD
Plate since	2019-06-29
Current registration	 WV58VZD
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-10-17
Last registration	2023-07-25
Complete history	See info



Registration #1	2008-10-17	27 mi
Registration #2	2011-09-08	13.903 mi
Registration #3	2012-09-06	19.851 mi
Registration #4	2013-08-15	23.298 mi
Registration #5	2014-08-29	28.877 mi
Registration #6	2015-09-02	37.338 mi
Registration #7	2016-07-01	42.537 mi
Registration #8	2017-06-05	49.659 mi
Registration #9	2017-06-06	49.659 mi
Registration #10	2019-06-06	55.377 mi
Registration #11	2019-06-06	55.377 mi
Registration #12	2019-06-06	55.377 mi
Registration #13	2019-06-06	55.377 mi
Registration #14	2019-06-06	55.377 mi
Registration #15	2019-06-06	55.377 mi
Registration #16	2019-06-06	55.377 mi
Registration #17	2019-06-06	55.377 mi
Registration #18	2019-06-06	55.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1287 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Engine number	2475072