




report date: 2024-03-29

General information

Make	BMW
Model	640 640D M SPORT GRAN COUPE
Colour	Silver
Year of manufacture	2016
Top speed	155 mph
0 - 60 mph	5.4 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	308 BHP
Max. torque	630 Nm at 1.500 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	57.7 mpg
Consumption combined	49.6 mpg
CO2 emission	152 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-10-18
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-03-08
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #7	2023-03-03 10:59
MOT test number	445442300086
Result	✓ Passed
Next expiry date	2024-03-08
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))

MOT #6	2022-02-28 15:35
MOT test number	510690742376
Result	✓ Passed

MOT #5	2021-03-09 17:22
MOT test number	526590979093
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2.6mm (5.2.3 (e))

MOT #4	2020-10-19 16:54
MOT test number	329934733492
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #3** 2020-10-19 12:10**MOT test number** 622862844358**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #2** 2019-10-22 08:59**MOT test number** 342556895223**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1** 2019-10-21 10:37**MOT test number** 852570316058**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✗
MOT

Expired:
8 March 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	8 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	SJ66XKZ
Plate since	2019-09-29
Current registration	SJ66XKZ
Plate since	2019-09-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-11-04
Last registration	2023-03-03
Complete history	See info



Registration #1	2016-11-04	8 mi
Registration #2	2019-10-21	18.711 mi
Registration #3	2019-10-22	18.712 mi
Registration #4	2020-10-19	22.225 mi
Registration #5	2020-10-19	22.225 mi
Registration #6	2020-10-19	22.225 mi
Registration #7	2020-10-19	22.225 mi
Registration #8	2020-10-19	22.225 mi
Registration #9	2020-10-19	22.225 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1894 mm
Height	1392 mm
Length	5007 mm
Wheel base	2968 mm
Kerb weight	1810 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	59519335