



KR08MEV

report date: 2024-03-29

General information

Make	AUDI
Model	A4 TDI SE TDV
Colour	Black
Year of manufacture	-
Top speed	131 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	46.3 mpg





MOT history

MOT #14	2020-10-27 09:49
MOT test number	409644564666
Result	✓ Passed
Next expiry date	2021-11-09

MOT #13	2020-10-26 12:32
MOT test number	589788142622
Result	✗ Failed
Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	
Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	

MOT #12	2019-10-30 14:04
MOT test number	585979667969
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2019-10-28 12:45
MOT test number	555811755396
Result	✗ Failed
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
Fail Front Registration plate inscription illegible (0.1 (b))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))	
Fail Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

**MOT #10** 2018-10-25 10:55**MOT test number** 620298634491**Result** ✓ Passed

Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9 2018-10-24 09:54**MOT test number** 157369484861**Result** ✗ Failed

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Side repeater not working (4.4.1 (a) (ii))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8 2017-11-10 11:05**MOT test number** 453572804765**Result** ✓ Passed**MOT #7** 2015-11-16 11:42**MOT test number** 476163251667**Result** ✓ Passed**MOT #6** 2015-11-13 15:31**MOT test number** 843688691452**Result** ✗ Failed

Fail Offside Front suspension has excessive play in a lower suspension ball joint front of pair (2.5.B.1a)

**MOT #5** 2015-03-06 11:08**MOT test number** 185895965453**Result** ✓ Passed**MOT #4** 2014-03-09 11:18**MOT test number** 759758264085**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2013-03-23 11:40**MOT test number** 438122783080**Result** ✓ Passed**MOT #2** 2012-03-10 10:50**MOT test number** 859550272065**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-03-14 10:13**MOT test number** 667643171029**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-04-23
Last registration	2020-10-27
Complete history	See info



Registration #1	2008-04-23	13 mi
Registration #2	2011-03-14	103.598 mi
Registration #3	2012-03-10	111.096 mi
Registration #4	2013-03-23	125.853 mi
Registration #5	2014-03-09	135.913 mi
Registration #6	2015-03-06	147.232 mi
Registration #7	2015-11-13	154.994 mi
Registration #8	2015-11-16	155.004 mi
Registration #9	2016-05-20	161.277 mi
Registration #10	2016-05-20	161.277 mi
Registration #11	2016-05-20	161.277 mi
Registration #12	2016-05-20	161.277 mi
Registration #13	2016-05-20	161.277 mi
Registration #14	2016-05-20	161.277 mi
Registration #15	2016-05-20	161.277 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1772 mm
Height	1427 mm
Length	4586 mm
Wheel base	2642 mm
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2

