





General information

Make	FIAT
Model	GRAND PUNTO MULTIJET SPORTING
Colour	Blue
Year of manufacture	-
Top speed	111 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	94 BHP	
Max. torque	125 Nm at 4.500 rpm	0 < 101 A
Cylinders	4	$101 - 120 \frac{B}{C}$
Fuel type	Diesel	121 - 140 E 141 - 165 F G
Consumption city	37.7 mpg	166 - 185 H
Consumption extra urban	62.8 mpg	186 - 225 J
Consumption combined	50.4 mpg	225+ L





Internet history

Entry 1

Date

2021-10-02

7

Pictures

Listing price

View report



source: autotrader.co.uk



WU59YCG report date: 2024-03-29

MOT history 2022-01-27 10:49 MOT test number 602698409316

	002090409510
Result	✓ Passed
Next expiry date	2023-02-01

MOT #13		2022-01-27 10:49
MOT test number		705240452245
Result		🗙 Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #12	2021-01-22 11:20
MOT test number	830888512777
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #11		2020-01-22 15:25
MOT test	number	100946753151
Result		✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	



W	U	5	9	Y	C	G
r	epo	rt d	ate:	20	24-0	3-29

MOT #10		2020-01-22 14:06
MOT test	number	770032029408
Result		🗙 Failed
Fail Ex	chaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Tyre slightly damaged tyre has cut outer side wall (5.2.3 (d) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	

МОТ #9	2019-01-17 15:13
MOT test number	655332062626
Result	✓ Passed

MOT #8	2019-01-16 12:18
MOT test number	634261283029
Result	🗙 Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #7	2018-02-02 13:06
MOT test number	260536261478
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #6		2016-09-07 11:45
MOT test	number	922344207809
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Oil leak	
Advice	Offside Rear Tyre worn close to the legal limit outer edge worn (4.1.E.1)	

MOT #5		2015-09-09 08:06
MOT test number		388750289024
Result		✓ Passed
Advice Nsr tyre	at 3mm	
Advice Nail in o	sr tyre shoulder	

MOT #4	2014-09-05 11:53
MOT test number	277678144239
Result	✓ Passed

MOT #3	2013-09-10 16:56
MOT test number	737533353292
Result	✓ Passed

MOT #2	2013-09-09 16:59
MOT test number	667932053232
Result	🗙 Failed
Fail Brake pedal anti-slip provision missing (3.3.A.1b)	
FailNearside Front coil spring fractured (2.4.C.1a)	





MOT #1	2012-09-01 14:12
MOT test number	247495742239
Result	Passed
Notice Both front tyres worn slightly on inner edges.	





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-01
Last registration	2022-01-27
Complete history	<u>See info</u>



Registration #1	2009-09-01	22 mi
Registration #2	2012-09-01	22.386 mi
Registration #3	2013-09-09	36.965 mi
Registration #4	2013-09-10	36.974 mi
Registration #5	2014-09-05	53.392 mi
Registration #6	2015-09-09	72.511 mi
Registration #7	2016-09-07	89.833 mi
Registration #8	2018-02-02	93.676 mi
Registration #9		11.777 mi
Registration #10		11.777 est
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		
5		11.777 est
Registration #14		11.227 es
		11.777 46 11.777 46 11.777 46





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1765 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	6128970