





### General information

Make	NISSAN
Model	PATROL DI SVE
Colour	Silver
Year of manufacture	2006
Top speed	99 mph
0 - 60 mph	15.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	158 BHP
Max. torque	379 Nm at 2.000 rpm
Engine capacity	2.953 сс
Cylinders	4
Fuel type	Diesel
Consumption city	19.8 mpg
Consumption extra urban	32.1 mpg
Consumption combined	26.2 mpg
CO2 emission	288 g/km
CO2 label	Μ







## Internet history

Entry 1

Date

Pictures

2021-12-21

35

Listing price

View report









source: cargurus.co.uk



# MOT history

MOT expiry date	2025-02-08
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	21
Total items failed	9

MOT #19	2024-02-09 10:11
MOT test number	747237698779
Result	🗸 Passed
Next expiry date	2025-02-08
<ul> <li>Advice Front Brakes imbalanced requirements only just met. It would appear the requires adjustment or repair. (1.2.1 (b) (i))</li> <li>Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))</li> </ul>	at the braking system

MOT #18	2024-01-31 12:53
MOT test number	429140913872
Result	× Failed
<b>Fail</b> Brake pedal has insufficient reserve travel (1.1.2 (a))	
Fail Front Brakes imbalanced across an axle (1.2.1 (b) (i))	
<b>Fail</b> Driver's seat fore and aft adjustment mechanism not functioning as intended. (6	6.2.5 (b) (i))
Advice Brake load sensing valve stiff (1.1.17 (c) (ii))	
Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))	





MOT #17		2023-03-02 14:04
MOT test	number	776757876253
Result		✓ Passed
Advice	Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive move	ment (5.3.4 (a) (i))
Advice	Offside rear inner wheel arch corroded.	
Advice	Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive mov	vement (5.3.4 (a) (i))
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #16		2022-02-18 12:12
MOT test	number	413997595604
Result		✓ Passed
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduce	ed (6.1.1 (c) (i))
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	

MOT #15		2021-03-12 15:19
MOT test	number	506241823926
Result		✓ Passed
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement	t (5.3.4 (a) (i))
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Surface corrosion to chassis and suspension components	

MOT #14	2020-02-19 10:13
MOT test number	720579059228
Result	✓ Passed





MOT #1	.3	2020-02-07 14:51
MOT te	st number	642715628472
Result		🗙 Failed
Fail	Nearside Rear Lower Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	
Fail	Horn sound not in accordance with requirements 2 different tones (7.7 (c))	
Fail	Offside Rear Lower Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))	

MOT #12		2019-02-27 08:12
MOT test	number	385907024224
Result		✓ Passed
Advice	Front Wheel bearing has slight play Nearside and offside $(5.1.3 (a) (i))$	
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #11	2019-02-26 11:57
MOT test number	952719337170
Result	× Failed
<b>Fail</b> Offside Front Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))	
Fail   Brake performance not tested (1.2.1 (g))	
Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
FailFuel pipe leaking (6.1.3 (b) (i))	
Advice Front Wheel bearing has slight play Nearside and offside (5.1.3 (a) (i))	

MOT #10		2018-03-07 16:06
MOT test	number	618716328644
Result		✓ Passed
Advice	Central Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Radiator support lower pannell corroded	





MOT #9	2017-02-28 11:50
MOT test number	517450600813
Result	✓ Passed
MOT #8	2016-03-03 12:36
MOT test number	222013823560
Result	✓ Passed
MOT #7	2015-02-26 12:43
MOT test number	908397755047
Result	✓ Passed
MOT #6	2014-02-11 15:23
MOT test number	268992844020
Result	✓ Passed
MOT #5	2013-03-08 15:46
MOT test number	339337263069
Result	✓ Passed
MOT #4	2012-02-29 15:39
MOT test number	645510062078
Result	✓ Passed
MOT #3	2011-02-22 12:52
MOT test number	485983751060
Result	✓ Passed
MOT #2	2010-03-04 11:53
MOT test number	131523960099
Result	✓ Passed





MOT #1	2009-06-16 14:40
MOT test number	422977969133
Result	✓ Passed



Tax & MOT check

√ Taxed	√ MOT
Tax due: 1 March 2025	Expires: 8 February 2025
Tax status	Valid until 1 March
Days left	306
MOT expiry date	8 February 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	Μ
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-





#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	VAMPL
Date	
Category	AMP
Туре	

#### Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 



FX06UXG report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-06-21
Last registration	2024-02-09
Complete history	See info



Registration #1	2006-06-21	21 mi
Registration #2	2009-06-16	29.731 mi
Registration #3	2010-03-04	35.792 mi
Registration #4	2011-02-22	46.282 mi
Registration #5	2012-02-29	51.041 mi
Registration #6	2013-03-08	55.934 mi
Registration #7	2014-02-11	59.885 mi
Registration #8	2015-02-26	65.311 mi
Registration #9	2016-03-03	69.772 mi
Registration #10	2017-02-28	73.816 mi
Registration #11	2018-03-07	78.165 mi
Registration #12		11.777 est
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		11.117 esi
Registration #20		11.117 est
Registration #21		11.227 esi

More info >





### Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
S0566	
\$0567	
S0569	

# Dimensions & weight

Width	1940 mm
Height	1855 mm
Length	5140 mm
Wheel base	2970 mm
Kerb weight	1380 kg
Max. allowed weight	3200 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	ZD30-206529