



HONDA

R06IXUG


report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD I-DTEC ES GT
Colour	Silver
Year of manufacture	2011
Top speed	129 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-18
Pictures	3
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-08
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	24
Total items failed	6

MOT #14 2023-10-26 14:40

MOT test number 530154798312

Result ✓ Passed

Next expiry date 2024-11-08

Minor Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt O/S and N/S (2.1.3 (g) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #13 2022-11-09 17:22

MOT test number 122539482530

Result ✓ Passed

MOT #12 2022-11-09 11:22

MOT test number 854310369289

Result ✗ Failed

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

MOT #11 2021-10-11 15:20

MOT test number 683182236076

Result ✓ Passed

Advice Nearside Front Play in steering rack inner joint(s)

**MOT #10** 2021-10-05 15:06**MOT test number** 607821665946**Result** ✗ Failed**Fail** Offside Front Upper Suspension component ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**MOT #9** 2020-10-06 13:26**MOT test number** 424237155313**Result** ✓ Passed**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2020-10-05 15:17**MOT test number** 887413213296**Result** ✗ Failed**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Play in steering rack inner joint(s)**MOT #7** 2019-09-17 15:44**MOT test number** 451100031597**Result** ✓ Passed**Advice** Nearside Play in steering rack inner joint(s)

**MOT #6** 2018-09-27 14:56**MOT test number** 406118314541**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

MOT #5 2017-10-04 13:39**MOT test number** 570476345731**Result** ✓ Passed

- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear tyre wearing on inner edge

MOT #4 2017-10-04 13:39**MOT test number** 759756885086**Result** ✗ Failed

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear tyre wearing on inner edge
- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #3 2016-09-30 12:22**MOT test number** 974590386908**Result** ✓ Passed



MOT #2	2015-09-25 11:58
MOT test number	972527563253
Result	✓ Passed
Advice	Offside Rear tyre bold on inner edge suspect close to exposing the cords
Advice	Nearside Rear tyre bold on inner edge suspect close to exposing the cords

MOT #1	2014-09-22 16:10
MOT test number	305015964258
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
8 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	8 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	RO61XUG
Plate since	2024-03-28
Current registration	RO61XUG
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-10-05
Last registration	2023-10-26
Complete history	See info



Registration #1	2011-10-05	8 mi
Registration #2	2014-09-22	43.963 mi
Registration #3	2015-09-25	55.979 mi
Registration #4	2016-09-30	68.469 mi
Registration #5	2017-10-04	80.020 mi
Registration #6	2017-10-04	80.020 mi
Registration #7	2018-09-27	90.989 mi
Registration #8	2019-09-17	99.873 mi
Registration #9	2020-09-22	108.767 mi
Registration #10	2021-09-22	117.661 mi
Registration #11	2022-09-22	126.555 mi
Registration #12	2023-09-22	135.449 mi
Registration #13	2024-09-22	144.343 mi
Registration #14	2025-09-22	153.237 mi
Registration #15	2026-09-22	162.131 mi
Registration #16	2027-09-22	171.025 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4740 mm
Wheel base	2705 mm
Kerb weight	1559 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	N22B13501677