



PXIOXYY

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Black
Year of manufacture	2010
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-08-04
Pictures	22
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-04-17
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	5
Total items failed	8

MOT #17	2024-04-16 11:37
MOT test number	539308702861
Result	✓ Passed
Next expiry date	2025-04-17
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2024-04-15 08:49
MOT test number	876053785074
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #15	2023-04-18 13:06
MOT test number	767762321474
Result	✓ Passed

**MOT #14** 2023-04-14 11:38**MOT test number** 208435972923**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #13** 2022-03-28 10:42**MOT test number** 620563074443**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2021-04-06 13:55**MOT test number** 687208019564**Result** ✓ Passed**MOT #11** 2020-04-17 10:38**MOT test number** 119013377257**Result** ✓ Passed**MOT #10** 2020-04-16 14:36**MOT test number** 744276941404**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #9	2019-04-24 13:11
--------	------------------

MOT test number	458041308120
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #8	2018-03-27 14:25
--------	------------------

MOT test number	722471495289
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #7	2017-03-30 14:25
--------	------------------

MOT test number	832776301698
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #6	2016-03-09 13:00
--------	------------------

MOT test number	843986812601
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #5	2016-03-08 10:58
--------	------------------

MOT test number	255537954580
-----------------	--------------

Result	✗ Failed
--------	----------

Fail	Nearside Front coil spring broken (2.4.C.1a)
------	----------------------------------------------

MOT #4	2015-03-26 16:31
--------	------------------

MOT test number	287495285095
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #3	2015-03-26 15:16
--------	------------------

MOT test number	536465185023
-----------------	--------------

Result	✗ Failed
--------	----------

Fail	Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
------	-----------------------------------------------------------------------------------------------------



MOT #2	2014-03-20 15:22
MOT test number	299239674096
Result	✓ Passed

MOT #1	2013-03-22 15:24
MOT test number	569411683058
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
17 April 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	17 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXX
XXXXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-31
Last registration	2024-04-16
Complete history	See info



Registration #1	2010-03-31	23 mi
Registration #2	2013-03-22	28.057 mi
Registration #3	2014-03-20	35.848 mi
Registration #4	2015-03-26	45.242 mi
Registration #5	2015-03-26	45.243 mi
Registration #6	2016-03-08	59.191 mi
Registration #7	2016-03-09	59.192 mi
Registration #8	2017-03-30	74.475 mi
Registration #9	2018-03-27	84.937 mi
Registration #10	2019-04-24	93.223 mi
Registration #11	2020-05-20	95.277 mi
Registration #12	2021-05-20	95.277 mi
Registration #13	2022-05-20	95.277 mi
Registration #14	2023-05-20	95.277 mi
Registration #15	2024-05-20	95.277 mi
Registration #16	2025-05-20	95.277 mi
Registration #17	2026-05-20	95.277 mi
Registration #18	2027-05-20	95.277 mi
Registration #19	2028-05-20	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 058721