





report date: 2024-03-29

General information

Make	BMW
Model	Z3 Z3 ROADSTER
Colour	Blue
Year of manufacture	1997
Top speed	128 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	180 Nm at 4.300 rpm
Engine capacity	1.895 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.2 mpg



CarCheck.co.uk page 1/16



Internet history

Entry 1

Date 2021-09-11

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/16



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-09-24
MOT pass rate	64 %
MOT passed	18
Failed MOT tests	10
Total advice items	64
Total items failed	10

MOT #28	2023-09-25 08:03
MOT test number	158214363337
Result	✓ Passed
Next expiry date	2024-09-24
Advice Fuel Pipe/s corroded	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Nearside Front Play in steering rack inner joint(s)	
Advice Nearside hole in rear wheel arch	

CarCheck.co.uk page 3/16



MOT #27 2023-09-15 13:19

MOT test number 722186655411

Result X Failed

Advice Fuel Pipe/s corroded

Advice Nearside hole in rear wheel arch

MAJOR Offside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen

(3.5 (a))

MAJOR Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Front Play in steering rack inner joint(s)

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MAJOR Offside Windscreen washer provides insufficient washer liquid (3.5 (a))

MAJOR Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #26 2022-08-25 11:16

MOT test number 801927346970

Advice Offside Front Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Rear Exhaust mounting defective rubber broken (6.1.2 (a))

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #25 2021-09-08 09:03

MOT test number 975386870739

Result \(\sqrt{Passed} \)

Advice Offside Front welding repairs heavily under sealed

CarCheck.co.uk page 4/16



MOT #24 2021-09-01 10:05

MOT test number 582542069467

Result

× Failed

MAJOR Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))

MOT #23 2021-08-23 10:36

MOT test number 205634075952

Result X Failed

MAJOR Windscreen washer not working (3.5 (a))

Advice Integral body structure is corroded but structural rigidity is not significantly reduced both sills soft (6.1.1 (c) (i))

MAJOR Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #22 2020-08-21 12:32

MOT test number 649130540660

CarCheck.co.uk page 5/16



MOT #21 2020-06-29 11:47

MOT test number 422128416862

Result X Failed

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

MAJOR Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MAJOR Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

MAJOR Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

MAJOR Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

MAJOR Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

MOT #20 2019-06-28 11:18

MOT test number 328679795390

Result
✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #19 2018-07-12 15:34

MOT test number 885291572902

Result \(\sqrt{Passed} \)

Minor Brake hose slightly damaged both rear (1.1.12 (b) (i))

Advice Rear brake pipes have slight corrosion

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Rust hole in n/s sill cover

CarCheck.co.uk page 6/16



MOT #18 2018-07-05 09:05

MOT test number 955928302984

Result X Failed

Minor Brake hose slightly damaged both rear (1.1.12 (b) (i))

MAJOR Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))

Advice Rear brake pipes have slight corrosion

MAJOR Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MAJOR Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

Advice Rust hole in n/s sill cover

MAJOR Nearside Front Position lamp not working (4.2.1 (a))

MAJOR Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

MOT #17 2017-07-04 08:45

MOT test number 146618211107

MOT #16 2017-07-03 13:08

MOT test number 805402870125

Result X Failed

Fail Offside Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)

Fail Nearside Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)

MOT #15 2016-07-06 07:56

MOT test number 815485908637

CarCheck.co.uk page 7/16



MOT #14 2015-07-13 16:41

MOT test number 245444295454

Result ✓ Passed

Notice Sill covers fitted

Notice Nail in offside rear tyre

Notice Play in steering rack inner joint(s)

Notice Under-trays fitted obscuring some underside components

MOT #13 2015-07-10 16:57

MOT test number 775751395139

Result X Failed

Notice Nail in offside rear tyre

Notice Play in steering rack inner joint(s)

Fail Nearside Rear coil spring broken (2.4.C.1a)

Notice Under-trays fitted obscuring some underside components

Notice Sill covers fitted

MOT #12 2014-08-28 16:59

MOT test number 118420444226

Result

Passed

Notice O/S/REAR SUBFRAME MOUNT BRACKET CORRODED

Notice O/S & N/S FRONT LOWER WISHBONE VOID BUSHES WORN

MOT #11 2013-07-26 17:09

MOT test number 996677203207

Result
✓ Passed

CarCheck.co.uk page 8/16



× Failed

MOT #10 2013-07-15 12:41

MOT test number 958316993164

Result X Failed

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

Fail Offside Rear Lower Suspension arm corroded and seriously weakened (2.4.G.1)

MOT #9 2012-07-13 09:08

MOT test number 457635092157

Result \square Passed

Notice N/s/r tyre worn close to the wear indicators in places

MOT #8 2011-07-29 13:10

MOT test number 309800711465

Result ✓ Passed

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #7 2010-07-30 11:06

MOT test number 102731210254

MOT #6 2010-07-30 09:30

MOT test number 673261010293

Fail Offside Front Tyre fouling a part of the vehicle (4.1.D.2)

Result

CarCheck.co.uk page 9/16



MOT #5 2009-07-15 13:29

MOT test number 633106599121

Result ✓ Passed

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Notice Oil leak

MOT #4 2008-08-01 09:25

MOT test number 502074218243

Result \square Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #3 2008-07-29 13:46

MOT test number 874801718244

Result X Failed

Fail Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Fail Offside Rear coil spring fractured (2.4.C.1a)

Pass with rectification Nearside Headlamp aim too high (1.8)

Fail Nearside Front Shock absorber has a serious fluid leak (2.7.3)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2007-07-20 10:57

MOT test number 503951407277

Result ✓ Passed

CarCheck.co.uk page 10/16



MOT #1

MOT test number

Result

Notice O/s/f anti roll bar link bush started to perish

Notice Front number plate cracked

Notice Slight play in o/s/f steering rack

CarCheck.co.uk page 11/16



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/16



Owner history

e union mestery	
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	

	More info >
Plate changes See in this check if this BMW had different number plates.	
Number of plates	
Correct registration	NK NA
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 13/16



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 14/16




page 15/16

Mileage check

CarCheck.co.uk

Odometer	In miles
Mileage registrations	30
First mileage registration	1997-08-29
Last registration	2023-09-25
Complete history	See info



Registration #1	1997-08-29	24 mi
Registration #2	2006-07-29	53.579 mi
Registration #3	2007-07-20	58.145 mi
Registration #4	2008-07-29	62.868 mi
Registration #5	2008-08-01	62.888 mi
Registration #6	2009-07-15	67.411 mi
Registration #7	2010-07-30	76.905 mi
Registration #8	2010-07-30	76.905 mi
Registration #9	2011-07-29	83.334 mi
Registration #10	2012-07-13	89.962 mi
Registration #11	2013-07-15	94.198 mi
Registration #12	2013-07-26	94.325 mi
Registration #13	2014-08-28	99.660 mi
Registration #14	2015-07-10	103.321 mi
Registration #15	2015-07-13	103.321 mi
Registration #16		77,777 46
Registration #17		11.117 es
Registration #18		77,777 46
Registration #19		11.177 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11,177 es
Registration #24		0.00 44
Registration #25		11.777 es
Registration #26		11.777 es

Registration #27	0.00 40
Registration #28	71.777 66
Registration #29	11.777 es
Registration #30	11.777 au

More info >



Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	*****
Video	see crash video



Additional information

-	
Fuel tank capacity	51
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	03448620

CarCheck.co.uk page 16/16