





report date: 2024-03-29

### General information

Make	NISSAN
Model	ALMERA
Colour	Blue
Year of manufacture	2006
Gearbox	-

# Engine & fuel consumption

Engine capacity	1.497 сс
Fuel type	Petrol
CO2 emission	160 g/km
CO2 label	G



CarCheck.co.uk page 1/15



report date: 2024-03-29

## Internet history

### Entry 1

Date 2022-02-13

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

# MOT history

MOT expiry date	2024-07-19
MOT pass rate	68 %
MOT passed	17
Failed MOT tests	8
Total advice items	32
Total items failed	14

MOT #25		2023-07-19 13:51
MOT test	number	226410585940
Result		✓ Passed
Next expi	y date	2024-07-19
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #24		2023-07-19 13:51
MOT test number		197350954825
Result		🗙 Failed
Advice Oil leak, but not	excessive (8.4.1 (a) (i))	
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #23		2022-07-19 14:27
MOT test	number	528961119130
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (	ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT test number

Result

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #21
 2021-07-13 15:03

 MOT test number
 370169412223

 Result
 ✓ Passed

MOT #20 2020-07-20 08:37
MOT test number 883929693256
Result ✓ Passed

 MOT #19
 2020-07-20 08:37

 MOT test number
 724529830846

 Result
 X Failed

**Pass with rectification** Nearside Headlamp has a product or reduced (4.1.4 (b))

Nearside Headlamp has a product on the lens so that the light output is severely

**Pass with rectification** Offside Headla reduced (4.1.4 (b))

Offside Headlamp has a product on the lens so that the light output is severely

CarCheck.co.uk page 4/15



report date: 2024-03-29

**MOT #18** 2019-07-17 11:42 **MOT** test number 263991211228 Result ✓ Passed **Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)) Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i)) **Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i)) **Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #17** 2019-07-17 08:48 154334106722 **MOT test number** Result ★ Failed Offside Front Position lamp not working (4.2.1 (a) (ii)) Fail Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i)) **Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)) **Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i)) Nearside Front Outer Track rod end ball joint dust cover excessively damaged or deteriorated so that Fail it no longer prevents the ingress of dirt (2.1.3 (g) (ii)) **Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #16	2018-07-17 13:50
MOT test number	628343951348
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT test number

Result

Advice Rear tyres perished cracked and in a poor condition

Advice Head light deflectors fitted

Advice Rear Brake pad(s) wearing thin appears to be on limits . discs also worn (3.5.1g)

MOT #14

MOT test number

426279111698

Result

Advice Rear tyres perished and cracking

MOT test number

694640881471

Result

Advice Rear tyres perished and cracking

Pass with rectification Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail Offside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)

Pass with rectification Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (1.1.C.1a)

 MOT #12
 2015-06-24 11:27

 MOT test number
 227765675133

 Result
 ✓ Passed

 MOT #11
 2014-07-31 17:47

 MOT test number
 329682014218

 Result
 ✓ Passed

CarCheck.co.uk page 6/15



report date: 2024-03-29

 MOT #10
 2014-07-23 17:23

 MOT test number
 885884804203

 Result
 ✓ Passed

 MOT #9
 2014-07-23 17:23

 MOT test number
 896114804207

 Result
 X Failed

 Pass with rectification
 Nearside Stop lamp not working (1.2.1b)

 MOT #8
 2014-03-25 14:12

 MOT test number
 508934984039

 Result
 ✓ Passed

 MOT #7
 2014-03-25 14:12

 MOT test number
 546014184005

 Result
 X Failed

 Pass with rectification
 Offside Rear Stop lamp not working (1.2.1b)

 MOT #6
 2013-03-25 12:18

 MOT test number
 577554983094

 Result
 ✓ Passed

MOT #5

MOT test number

758990492009


Result

Advice Nearside Power steering component(s) has slight seepage from a component (2.3.3b)

CarCheck.co.uk page 7/15



report date: 2024-03-29



MOT #3		2010-03-24 15:03
MOT test number		253733880003
Result		<b>✓</b> Passed
MOT #2		2010-03-24 10:48
MOT test number		591783080003
Result		<b>×</b> Failed
Pass with rectification	Offside Headlamp aim too high (1.8)	
Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)		
Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)		

MOT #1		2009-03-19 15:06
MOT test	number	473048779014
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 8/15



report date: 2024-03-29

# Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	19 July 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

_	
Owner	hictory
OWITEI	HISLULY

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		AN
*******		
***************************************		
	More info	>
Plate changes		
See in this check if this NISSAN had different number plates.		
Number of plates		
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 12/15



report date: 2024-03-29

### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2006-04-14
Last registration	2023-07-19
Complete history	See info



Registration #1	2006-04-14	24 mi
Registration #2	2009-03-19	29.606 mi
Registration #3	2010-03-24	35.979 mi
Registration #4	2010-03-24	35.979 mi
Registration #5	2011-03-28	43.375 mi
Registration #6	2012-03-30	50.495 mi
Registration #7	2013-03-25	56.913 mi
Registration #8	2014-03-25	63.255 mi
Registration #9	2014-07-23	65.654 mi
Registration #10	2014-07-31	65.654 mi
Registration #11	2015-06-24	74.711 mi
Registration #12	2016-07-21	85.484 mi
Registration #13	2016-07-21	85.485 mi
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		71.777 es
Registration #20		71.777 es
Registration #21		71.777 es
Registration #22		71.777 es
Registration #23		11.777 es
Registration #24		71.777 es
Registration #25		0.00 44



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Additional information

Engine number GA16-566159

CarCheck.co.uk page 15/15