



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA SRI NAV 16V
Colour	Black
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-20
Pictures	5
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #20	2022-05-09 14:34
MOT test number	610849934866
Result	✓ Passed
Next expiry date	2023-05-10
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #19	2022-05-09 13:02
MOT test number	656641903561
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Fail	Offside Front Road wheel fixing missing (5.2.1 (a) (i))
Fail	Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Fail	Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))

MOT #18	2021-05-11 10:31
MOT test number	871897686839
Result	✓ Passed

**MOT #17**

2021-05-03 13:42

MOT test number

521123693347

Result**✗ Failed**

- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Valve stem seriously damaged (5.2.3 (j))
- Fail** Brake performance not tested Due to fluid leak (1.2.1 (g))
- Fail** Offside Rear Valve stem seriously damaged (5.2.3 (j))
- Fail** Offside Rear Shock absorbers has negligible damping effect (5.3.2 (d))
- Fail** Nearside Brake pipe leaking on a hydraulic braking system front to rear leaking and corroded all the way to the flexi (1.1.11 (b) (ii))
- Fail** Offside Brake pipe excessively corroded front to rear all the way to the flexi pipe (1.1.11 (c))
- Fail** Offside Front Valve stem seriously damaged (5.2.3 (j))
- Fail** Nearside Rear Shock absorbers has negligible damping effect (5.3.2 (d))

MOT #16

2020-03-12 15:12

MOT test number

609940137540

Result**✓ Passed****MOT #15**

2018-07-26 09:33

MOT test number

843096486268

Result**✓ Passed**

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #14** 2017-08-02 13:21**MOT test number** 208461029176**Result** ✓ Passed**MOT #13** 2017-08-01 10:35**MOT test number** 339832160759**Result** ✗ Failed

- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Front coil spring broken (2.4.C.1a)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Fail** Nearside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #12 2017-07-31 13:36**MOT test number** 498184532781**Result** ✗ Failed

- Fail** Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Offside Front coil spring broken (2.4.C.1a)
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)

MOT #11 2016-07-19 12:57**MOT test number** 185105126894**Result** ✓ Passed

- Advice** Brake pipe slightly corroded o/s to n/s rear (3.6.B.2c)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10** 2016-07-19 12:57**MOT test number** 192329350468**Result** ✗ Failed**Pass with rectification** Front passenger door cannot be opened from outside the vehicle (6.2.B.1b)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Brake pipe slightly corroded o/s to n/s rear (3.6.B.2c)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #9** 2015-07-10 14:41**MOT test number** 275581395414**Result** ✓ Passed**MOT #8** 2015-07-10 09:59**MOT test number** 667311495170**Result** ✗ Failed**Notice** Nail in nearside front tyre**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Notice** Nail in nearside rear tyre**MOT #7** 2014-04-07 14:49**MOT test number** 348137194015**Result** ✓ Passed**MOT #6** 2014-04-07 12:27**MOT test number** 766687294085**Result** ✗ Failed**Fail** Offside Rear coil spring fractured (2.4.C.1a)

**MOT #5** 2013-04-05 12:24**MOT test number** 329825793015**Result** ✓ Passed**MOT #4** 2012-03-27 15:05**MOT test number** 169477782076**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Oil leak**MOT #3** 2012-03-27 15:05**MOT test number** 247607582090**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Notice** Oil leak**Pass with rectification** Offside Front Headlamp aim too low (1.8)**MOT #2** 2011-03-15 14:47**MOT test number** 476104771094**Result** ✓ Passed**Notice** Oil leak**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** O/s/f and n/s/f tyre treads low [2mm]



MOT #1	2010-04-01 10:51
MOT test number	941211490096
Result	✓ Passed
<div>Notice Oil leak</div>	



Damage history


Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	MM07NYA
Plate since	2019-03-29
Current registration	MM07NYA
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-06-29
Last registration	2022-05-09
Complete history	See info



Registration #1	2007-06-29	19 mi
Registration #2	2010-04-01	21.692 mi
Registration #3	2011-03-15	35.657 mi
Registration #4	2012-03-27	49.979 mi
Registration #5	2013-04-05	56.116 mi
Registration #6	2014-04-07	62.113 mi
Registration #7	2014-04-07	62.113 mi
Registration #8	2015-07-10	68.975 mi
Registration #9	2015-07-10	68.975 mi
Registration #10	2016-07-19	75.470 mi
Registration #11	2016-07-19	75.470 mi
Registration #12	2016-07-19	75.470 mi
Registration #13	2016-07-19	75.470 mi
Registration #14	2016-07-19	75.470 mi
Registration #15	2016-07-19	75.470 mi
Registration #16	2016-07-19	75.470 mi
Registration #17	2016-07-19	75.470 mi
Registration #18	2016-07-19	75.470 mi
Registration #19	2016-07-19	75.470 mi
Registration #20	2016-07-19	75.470 mi
Registration #21	2016-07-19	75.470 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20JV1118