



General information

Make	FORD
Model	C-MAX ZETEC 115
Colour	Blue
Year of manufacture	2010
Top speed	116 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	280 Nm at 1.900 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 2

Date	2021-08-29
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-08-28
Pictures	25
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2022-10-12
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	39
Total items failed	0

MOT #12	2021-10-13 12:31
MOT test number	478955561105
Result	✓ Passed
Next expiry date	2022-10-12
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #11	2021-10-11 07:06
MOT test number	399316756771
Result	✗ Failed
DANGEROUS	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
MAJOR	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10	2020-11-21 11:15
MOT test number	522308329617
Result	✓ Passed

**MOT #9** 2020-11-13 17:08**MOT test number** 481038128157**Result** ✗ Failed**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #8** 2019-05-22 11:51**MOT test number** 317762908924**Result** ✓ Passed**Advice** Nearside Front Nail in tyre**MOT #7** 2019-05-08 15:29**MOT test number** 313542826286**Result** ✗ Failed**MAJOR** Offside Front Inner Suspension arm pin or bush excessively worn rear of the two bushes (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Nail in tyre**MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MAJOR** Nearside Front Inner Suspension arm pin or bush excessively worn Rear of the two bushes (5.3.4 (a) (i))

**MOT #6** 2018-07-09 07:53**MOT test number** 935245773267**Result** ✓ Passed

- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Oil leak off side front of engine timing covers area
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

**MOT #5** 2017-07-06 11:54**MOT test number** 794202318374**Result** ✓ Passed

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**Advice** Offside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement both bushes (2.4.G.2)

**Advice** Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement forward arm both bushes (2.4.G.2)

**Advice** Oil leak n/s drive shaft oil seal

**Advice** Nearside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement both bushes (2.4.G.2)

**Advice** Nearside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement forward arm both bushes (2.4.G.2)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #4** 2016-06-17 13:28**MOT test number** 955867154428**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #3** 2015-06-01 13:43**MOT test number** 559392455188**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Play in steering rack inner joint(s)**MOT #2** 2014-06-21 12:48**MOT test number** 369742874125**Result** ✓ Passed**Notice** Advise damage to offside front tyre .**MOT #1** 2013-05-24 12:44**MOT test number** 535994043176**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>WL10JSV</b>
Plate since	2019-03-28
Current registration	<b>WL10JSV</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-07-09
Last registration	2021-10-13
Complete history	<a href="#">See info</a>



Registration #1	2010-07-09	10 mi
Registration #2	2013-05-24	47.726 mi
Registration #3	2014-06-21	67.442 mi
Registration #4	2015-06-01	81.990 mi
Registration #5	2016-06-17	108.831 mi
Registration #6	2017-07-06	126.843 mi
Registration #7	2018-07-09	139.236 mi
Registration #8	2019-05-08	145.447 mi
Registration #9	2020-05-20	151.277 mi
Registration #10	2021-05-20	157.277 mi
Registration #11	2022-05-20	163.277 mi
Registration #12	2023-05-20	169.277 mi
Registration #13	2024-05-20	175.277 mi
Registration #14	2025-05-20	181.277 mi
Registration #15	2026-05-20	187.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1491 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	AU08714