





### General information

Make	LAND ROVER
Model	DEFENDER TD PICK UP
Colour	Red
Year of manufacture	2012
Top speed	90 mph
0 - 100 km/h	15.8 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	90 kW / 123 HP / 122 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.198 сс
Cylinders	4
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	31.0 mpg
Consumption combined	28.3 mpg
CO2 emission	266 g/km
CO2 label	Μ







## Internet history

Entry 1

Date

2022-03-17 9

Pictures

Listing price

-

View report



source: cargurus.co.uk









## MOT history

MOT expiry date	2025-04-05
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	13
Total items failed	8

MOT #12	2024-03-19 12:34
MOT test number	129572417620
Result	✓ Passed
Next expiry date	2025-04-05

MOT #11	2023-04-06 08:36
MOT test number	892086617739
Result	✓ Passed

MOT #10	2023-03-28 10:40	
MOT test number	672658709057	
Result	× Failed	
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))		
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))		
<b>Pass with rectification</b> Offside Headlamp aim too low Adjusted (4.1.2 (a))		
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
FailService brake efficiency below requirements (1.2.2 (a) (i))		
Advice Rear Lower Shock absorbers has a slightly worn bush O/S & N/S (5.3.2 (c))		
Advice Nearside Front Hub knuckle oil seal leaking badly		





MOT #9	2022-04-05 09:04
MOT test number	224667727793
Result	✓ Passed
MOT #8	2021-11-09 13:02
MOT test number	235802989750
Result	✓ Passed
MOT #7	2020-10-08 13:53

		2020-10-00 13.33
MOT tes	t number	345037943899
Result		✓ Passed
Advice	Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))	

MOT #6		2019-10-03 09:18
MOT test	number	252198199149
Result		✓ Passed
Advice	Front Power steering pipe/hose slightly corroded (2.1.5 (g) (i))	
Advice	Centre silencer has been removed	



Ρ	<b>E62</b>	2K		X
	report da	ate: 20	24-03	3-29

MOT #5	2019-10-02 10:34
MOT test number	942949867132
Result	🗙 Failed
Fail Nearside Headlamp not working on dipped beam and o/s (4.1.1 (a) (ii))	
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
<b>Fail</b> Service brake efficiency below requirements (1.2.2 (a) (i))	
Advice Centre silencer has been removed	
Fail Headlamp not working on main beam n/s and o/s (4.1.1 (a) (ii))	
Advice Front Power steering pipe/hose slightly corroded (2.1.5 (g) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	) (ii))

MOT #4	2018-09-24 17:14
MOT test number	952028904636
Result	✓ Passed

MOT #3	2017-09-27 08:44
MOT test number	319447606633
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #2	2016-09-20 12:24
MOT test number	710496586329
Result	✓ Passed

MOT #1	2015-09-15 11:31
MOT test number	797108535645
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	✓ MOT Expires: 5 April 2025
Tax status	Valid until 1 October
Days left	154
MOT expiry date	5 April 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE C
Category	 Lamp
Туре	
Damage 2	AMPLE
Date	
Category	 AMPLI
Туре	W CON

#### Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





## Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********		
ANALYSING AND ANALYSING ANA		
***********		
********		
	More info	>
Plate changes		

Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-28
Last registration	2024-03-19
Complete history	See info



Registration #1	2012-09-28	27 mi
Registration #2	2015-09-15	37.281 mi
Registration #3	2016-09-20	47.869 mi
Registration #4	2017-09-27	49.825 mi
Registration #5	2018-09-24	51.238 mi
Registration #6	2019-10-02	56.346 mi
Registration #7	2019-10-03	56.350 mi
Registration #8		11.777 est
Registration #9		11.777 est
Registration #10		11.777 esi
Registration #11		11.777 est
Registration #12		
Registration #13		01.000 est



## Dimensions & weight

Width	1790 mm
Height	2000 mm
Length	3722 mm
Wheel base	2360 mm
Kerb weight	1738 kg
Max. allowed weight	2505 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	120517122408DT224