



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Silver
Year of manufacture	2007
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H







Internet history

Entry 2


Date	2021-03-08
Pictures	39
Listing price	View report



source: [yesauto.com](#)

Entry 1

Date	2021-02-05
Pictures	39
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2025-01-29
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	79
Total items failed	10

MOT #23	2024-01-29 12:34
---------	------------------

MOT test number	563468962861
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-01-29
------------------	------------

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge on edges (5.2.3 (e))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge on edges (5.2.3 (e))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))

**MOT #22**

2023-01-30 15:41

MOT test number

185356231158

Result

✓ Passed

- Advice** Rear exhaust heat shield loose but secure
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face heavily corroded (1.1.14 (a) (ii))
- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking between tread (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face heavily corroded (1.1.14 (a) (ii))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

**MOT #21**

2023-01-30 15:05

MOT test number

236577033286

Result**✗ Failed**

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face heavily corroded (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Rear exhaust heat shield loose but secure
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face heavily corroded (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking between tread (5.2.3 (d) (ii))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #20

2021-10-18 15:08

MOT test number

150225178612

Result**✓ Passed**

- Advice** Exhaust shield loose
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn inner and outer edge (5.2.3 (e))

**MOT #19**

2020-10-15 10:00

MOT test number

617308120943

Result

✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Brake pad(s) wearing thin on limit (1.1.13 (a) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #18

2020-10-15 09:06

MOT test number

636853965519

Result

✗ Failed

MAJOR Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MAJOR Rear Registration plate inscription illegible (0.1 (b))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Brake pad(s) wearing thin on limit (1.1.13 (a) (ii))

MAJOR Front Registration plate inscription illegible (0.1 (b))

MOT #17

2019-04-20 13:15

MOT test number

318754473750

Result

✓ Passed

Advice Rear brake pads worn low

Advice Nearside Rear Tyre has a nail in the tread /side wall badly perished

**MOT #16**

2019-04-20 13:15

MOT test number

308525935682

Result**✗ Failed****Advice** Rear brake pads worn low**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Tyre has a nail in the tread /side wall badly perished**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #15**

2018-04-19 12:38

MOT test number

603689489212

Result**✓ Passed****Advice** Nearside & offside front tyres are worn on the inner & outer edges**Advice** Exhaust heat shield is loose**MOT #14**

2018-04-19 09:00

MOT test number

623526716961

Result**✗ Failed****Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**Advice** Exhaust heat shield is loose**Advice** Nearside & offside front tyres are worn on the inner & outer edges**MOT #13**

2017-04-18 16:07

MOT test number

868276629745

Result**✓ Passed****Advice** Front brakes have run out

**MOT #12** 2017-04-18 10:53**MOT test number** 918924642890**Result** ✗ Failed**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Advice** Front brakes have run out**Fail** Service brake: efficiency below requirements (3.7.B.7)**MOT #11** 2016-04-19 15:55**MOT test number** 206192417202**Result** ✓ Passed**Advice** Front brakes have fluctuation**MOT #10** 2016-04-19 11:54**MOT test number** 659749840095**Result** ✗ Failed**Advice** Front brakes have fluctuation**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**MOT #9** 2015-03-28 12:27**MOT test number** 736407885091**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2015-03-28 09:31**MOT test number** 655697085081**Result** ✗ Failed**Fail** Offside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2014-06-04 16:46**MOT test number** 768365254183**Result** ✓ Passed

- Notice** N/s door mirror glass damaged
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** O/s/r tyre worn
- Notice** O/s and n/s/f tyres worn

MOT #6 2013-06-04 14:50**MOT test number** 248525053493**Result** ✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2013-05-15 11:34**MOT test number** 308615433177**Result** ✗ Failed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



MOT #4	2012-05-23 14:09
MOT test number	608204842176
Result	✓ Passed

MOT #3	2012-05-23 10:37
MOT test number	217184042100
Result	✗ Failed
<div><div>Fail</div>Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)</div>	

MOT #2	2011-05-26 15:12
MOT test number	486116541154
Result	✓ Passed
<div><div>Notice</div>Inter cooler pipe weeping</div> <div><div>Notice</div>Front tyres feathered on edges</div> <div><div>Notice</div>Rattle from air cleaner</div>	

MOT #1	2010-06-08 11:23
MOT test number	220899050476
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
29 January 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	29 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-05-31
Last registration	2024-01-29
Complete history	See info



Registration #1	2007-05-31	25 mi
Registration #2	2010-06-08	36.764 mi
Registration #3	2011-05-26	43.591 mi
Registration #4	2012-05-23	52.196 mi
Registration #5	2012-05-23	52.196 mi
Registration #6	2013-05-15	58.981 mi
Registration #7	2013-06-04	59.347 mi
Registration #8	2014-06-04	65.056 mi
Registration #9	2015-03-28	71.391 mi
Registration #10	2015-03-28	71.391 mi
Registration #11	2016-04-19	74.808 mi
Registration #12	2016-04-19	74.808 mi
Registration #13	2017-04-18	78.441 mi
Registration #14	2018-05-29	81.377 mi
Registration #15	2019-05-29	85.377 mi
Registration #16	2020-05-29	89.377 mi
Registration #17	2021-05-29	93.377 mi
Registration #18	2022-05-29	97.377 mi
Registration #19	2023-05-29	101.377 mi
Registration #20	2024-01-29	105.377 mi
Registration #21	2024-01-29	105.377 mi
Registration #22	2024-01-29	105.377 mi
Registration #23	2024-01-29	105.377 mi
Registration #24	2024-01-29	105.377 mi
Registration #25	2024-01-29	105.377 mi
Registration #26	2024-01-29	105.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1904 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	7C12619