





report date: 2024-03-28

## General information

Make	LAND ROVER	
Model	RANGE ROVER TDV8 VOGUE SE	
Colour	Black	
Year of manufacture	2011	
Top speed	130 mph	
0 - 100 km/h	7.8 seconds	
Gearbox	6 speed automatic	

## Engine & fuel consumption

Power	230 kW / 313 HP / 313 BHP
Max. torque	700 Nm at 1.500 rpm
Engine capacity	4.367 cc
Cylinders	8
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	34.5 mpg
Consumption combined	30.1 mpg
CO2 emission	253 g/km
CO2 label	L



CarCheck.co.uk page 1/13



## Internet history

## Entry 2

Date 2021-07-08

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-07-06	
Pictures	1	
Listing price	View report	



source: autotrader.co.uk

CarCheck.co.uk page 2/13



✓ Passed

M	$OT^-$	history
- 141	$\circ$	IIISLUIV

Result

MOT expiry date	2024-11-27
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	19
Total items failed	1
MOT #13	2023-11-28 09:45
MOT test number	697466037749
Result	<b>✓</b> Passed
Next expiry date	2024-11-27
MOT #12	2022-11-15 15:52
MOT test number	253458154223
Result	<b>✓</b> Passed
MOT #11	2022-02-21 15:40
MOT test number	272958787696
Result	<b>✓</b> Passed
MOT #10	2021-07-01 08:02
MOT test number	120583126626

MOT #9	2021-02-01 14:40
MOT test number	882495999474
Result	✓ Passed

CarCheck.co.uk page 3/13



**Advice** 

Oil leak, but not excessive (8.4.1 (a) (i))

LD11VJA report date: 2024-03-28

MOT test number

185134025425

Result

Advice (i))

Minor

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice
(a) (i))

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #7

MOT test number

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6

MOT test number

438553961570

Result

Advice Under trays fitted underneath.

Advice Items removed from driver's view prior to test

CarCheck.co.uk page 4/13



**MOT #5** 2017-03-13 10:49

**MOT test number** 522810077648

Result \sqrt{Passed}

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Advice** Offside Front Suspension arm has slight play in a pin/bush back wishbone (2.4.G.2)

**Advice** Offside front seat belt needs slight help to retract.

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

front wishbone (2.4.G.2)

**Advice** Nearside Front Suspension arm has slight play in a pin/bush back wishbone (2.4.G.2)

**Advice** Front brake discs lipped and slightly worn

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

front wishbone (2.4.G.2)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #4 2016-02-04 16:45

MOT test number 353521426953

Result \( \sqrt{Passed} \)

MOT #3 2016-01-22 15:53

MOT test number 220138145248

**Result** ★ Failed

**Advice** Front brake discs are worn and lipped

**Advice** Engine covers and under trays fitted obscuring some components

Fail Nearside Power steering pipe(s) or hose(s) fouling other parts of the vehicle TOUCHING SUBFRAME /

INSECURE (2.3.2)

**Advice** Both rear tyres are cracking on outer shoulder

CarCheck.co.uk page 5/13



MOT #2

MOT test number

156946235492

Result

Notice Oil leak

2015-02-05 15:38

 MOT #1
 2014-03-17 14:00

 MOT test number
 546556874042

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



## Tax & MOT check





Expires: 27 November 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	27 November 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 7/13



### Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



#### Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



### Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner	بمنحاء أحا
UWNER	nistary
OVVIICI	IIISCUIV

For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download to	
***************************************	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	
Current registration	OK SIE SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



### Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 11/13



## Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-29
Last registration	2023-11-28
Complete history	See info



Registration #1	2011-03-29	24 mi
Registration #2	2014-03-17	14.233 mi
Registration #3	2015-02-05	18.791 mi
Registration #4	2016-01-22	23.584 mi
Registration #5	2016-02-04	23.932 mi
Registration #6	2017-03-13	30.975 mi
Registration #7	2018-03-08	37.402 mi
Registration #8	2019-03-18	44.638 mi
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		11.777 mi
Registration #14		11.777 es
Registration #15		11.777 mi
Registration #16		11.177 au

More info >

page 12/13 CarCheck.co.uk



## Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	2216 mm
Height	1865 mm
Length	4967 mm
Wheel base	2880 mm
Kerb weight	2710 kg
Max. allowed weight	3200 kg

## Additional information

Fuel tank capacity	100
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0006899448DT

CarCheck.co.uk page 13/13