



SH6ISKX

report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	White
Year of manufacture	-
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-04
Pictures	15
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #14	2022-10-17 16:45
MOT test number	815462581129
Result	✓ Passed
Next expiry date	2023-10-29
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2022-10-15 09:03
MOT test number	583266608198
Result	✗ Failed
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #12** 2021-10-28 15:06**MOT test number** 592860476052**Result** ✓ Passed**Minor** Nearside Side repeater lens defective which has no effect on emitted light broken (4.4.1 (b) (i))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**MOT #11** 2020-10-29 09:51**MOT test number** 236230204897**Result** ✓ Passed**MOT #10** 2019-04-30 14:48**MOT test number** 163781789419**Result** ✓ Passed**MOT #9** 2018-04-13 12:17**MOT test number** 652372208355**Result** ✓ Passed**MOT #8** 2018-04-13 07:59**MOT test number** 347671790567**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #7** 2017-04-06 14:26**MOT test number** 347322319488**Result** ✓ Passed

- Advice** Offside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)
- Advice** Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)
- Advice** Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2017-04-05 16:21**MOT test number** 773334321711**Result** ✗ Failed

- Advice** Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front Headlamp aim too high (1.8)
- Advice** Offside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)

MOT #5 2016-04-08 15:24**MOT test number** 483464069158**Result** ✓ Passed

- Advice** Emissions to clean for machine -PASS-
- Advice** Clutch biting point low
- Advice** Offside rear tyre worn on inner edge 185/65/15

**MOT #4** 2016-04-08 13:48**MOT test number** 988376214192**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside rear tyre worn on inner edge 185/65/15**Advice** Emissions to clean for machine -PASS-**Fail** Nearside Headlamp not working on dipped beam 477 bulb (1.7.5a)**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Clutch biting point low**MOT #3** 2015-04-30 16:53**MOT test number** 135410325198**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2015-04-30 14:58**MOT test number** 879310425180**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Nail in nearside rear tyre**Fail** Offside Stop lamp not working (1.2.1b)



MOT #1	2014-11-03 10:56
MOT test number	297617304377
Result	✓ Passed
Notice	Fuel injector seal leaking exhaust gases
Notice	Both front day running lights inoperative



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	SH61SKX
Plate since	2019-09-29
Current registration	SH61SKX
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-11-29
Last registration	2022-10-17
Complete history	See info



Registration #1	2011-11-29	12 mi
Registration #2	2014-11-03	30.807 mi
Registration #3	2015-04-30	33.400 mi
Registration #4	2015-04-30	33.400 mi
Registration #5	2016-04-08	47.190 mi
Registration #6	2016-04-08	47.190 mi
Registration #7	2017-04-05	57.291 mi
Registration #8	2017-04-06	57.291 mi
Registration #9	2017-04-06	57.291 mi
Registration #10	2017-04-06	57.291 mi
Registration #11	2017-04-06	57.291 mi
Registration #12	2017-04-06	57.291 mi
Registration #13	2017-04-06	57.291 mi
Registration #14	2017-04-06	57.291 mi
Registration #15	2017-04-06	57.291 mi
Registration #16	2017-04-06	57.291 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	4259452