



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Black
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	180 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-02-15
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2025-02-28
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	27
Total items failed	9

MOT #20	2024-02-26 14:43
MOT test number	843912120158
Result	✓ Passed
Next expiry date	2025-02-28
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #19	2023-02-24 14:37
MOT test number	880541489883
Result	✓ Passed

MOT #18	2022-03-01 08:41
MOT test number	786976142198
Result	✓ Passed

MOT #17	2021-07-01 14:27
MOT test number	828107971003
Result	✓ Passed
Advice	Corrosion to inside face of front discs

**MOT #16**

2021-06-30 14:17

**MOT test number**

213766045460

**Result****✗ Failed****Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nail o/s/r tyre**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Corrosion to inside face of front discs**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (iii))**MOT #15**

2020-07-02 09:09

**MOT test number**

300286974052

**Result****✓ Passed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #14**

2020-07-01 14:05

**MOT test number**

889384156796

**Result****✗ Failed****Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Stop lamp(s) not working high level brake light (4.3.1 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13**

2019-07-01 11:17

**MOT test number**

763901138992

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear tyre cracking on side wall
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge tyre cracking on side wall (5.2.3 (e))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12**

2018-07-02 10:54

**MOT test number**

274223710587

**Result**

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge tyre cracking on side wall (5.2.3 (e))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre cracking on side wall (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #11**

2017-06-27 15:23

**MOT test number**

375516005754

**Result**

✓ Passed

**MOT #10**

2017-02-28 17:07

**MOT test number**

732499492539

**Result**

✓ Passed

- Advice** Engine oil breather split causing fumes

**MOT #9** 2017-02-28 14:40**MOT test number** 407425172451**Result** ✗ Failed**Fail** Rear fog lamp not working (1.3.2b)**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Engine oil breather split causing fumes**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #8** 2015-12-03 14:23**MOT test number** 300064294222**Result** ✓ Passed**MOT #7** 2014-04-17 15:27**MOT test number** 175577504160**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2013-04-02 17:10**MOT test number** 578602993043**Result** ✓ Passed**MOT #5** 2013-04-02 16:15**MOT test number** 787702093072**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Nearside rear tyre splitting on tread not to cords



MOT #4	2012-03-28 11:04
MOT test number	697278382022
Result	✓ Passed
MOT #3	2012-03-28 10:04
MOT test number	338088482059
Result	✗ Failed
<div><div>Fail</div>Rear fog lamp not working (1.3.2b)</div>	
MOT #2	2011-03-23 11:19
MOT test number	685942081090
Result	✓ Passed
MOT #1	2010-03-15 15:30
MOT test number	413234670046
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
28 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	28 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>PK07AYW</b>
Plate since	2024-03-29
Current registration	 <b>PK07AYW</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-09
Last registration	2024-02-26
Complete history	<a href="#">See info</a>



Registration #1	2007-03-09	18 mi
Registration #2	2010-03-15	17.024 mi
Registration #3	2011-03-23	20.886 mi
Registration #4	2012-03-28	26.360 mi
Registration #5	2012-03-28	26.360 mi
Registration #6	2013-04-02	28.522 mi
Registration #7	2013-04-02	28.522 mi
Registration #8	2014-04-17	33.196 mi
Registration #9	2015-12-03	43.370 mi
Registration #10	2017-02-28	50.173 mi
Registration #11	2017-02-28	50.174 mi
Registration #12	2018-03-20	55.277 mi
Registration #13	2018-03-20	55.277 mi
Registration #14	2019-03-20	55.277 mi
Registration #15	2019-03-20	55.277 mi
Registration #16	2020-03-20	55.277 mi
Registration #17	2020-03-20	55.277 mi
Registration #18	2021-03-20	55.277 mi
Registration #19	2021-03-20	55.277 mi
Registration #20	2022-03-20	55.277 mi
Registration #21	2022-03-20	55.277 mi
Registration #22	2024-02-26	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1314 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BFS 056261