



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D3 SE LUX
Colour	White
Year of manufacture	2015
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	62.8 mpg
CO2 emission	118 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-12-26
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-02
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	14
Total items failed	16

MOT #10	2023-08-03 13:14
MOT test number	224877877598
Result	✓ Passed
Next expiry date	2024-08-02

MOT #9	2023-07-22 09:16
MOT test number	670789519640
Result	✗ Failed

- Fail** Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))
- Fail** Offside Front Outer Drive shaft joint excessively worn (6.1.7 (c) (i))
- Fail** Offside Windscreen wiper not working (3.4 (a))
- Fail** Nearside Side repeater missing (4.4.1 (a) (ii))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #8	2022-06-14 14:04
MOT test number	603522264325
Result	✓ Passed

**MOT #7**

2022-06-09 08:42

MOT test number

648445074527

Result

✗ Failed

- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Fail** Nearside Headlamp aim not tested (4.1.2 (b))

MOT #6

2021-09-25 09:12

MOT test number

582186355401

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** T.P.M.S Light on not indicating a fault
- Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5**

2021-09-22 12:35

MOT test number

984925053528

Result**✗ Failed****Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #4**

2020-10-02 11:04

MOT test number

333206405518

Result**✓ Passed****Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Driver's view Items removed from driver's view prior to test Removed air fresheners and file from driver's view and placed on passenger front seat (3.1 (a) (ii))**MOT #3**

2020-10-02 11:04

MOT test number

850602734603

Result**✗ Failed****Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Driver's view Items removed from driver's view prior to test Removed air fresheners and file from driver's view and placed on passenger front seat (3.1 (a) (ii))



MOT #2	2019-10-03 08:41
MOT test number	159872997166
Result	✓ Passed
MOT #1	2018-10-04 08:46
MOT test number	313021522425
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
2 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	2 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-22
Last registration	2023-08-03
Complete history	See info



Registration #1	2015-09-22	9 mi
Registration #2	2018-10-04	74.412 mi
Registration #3	2019-10-03	98.439 mi
Registration #4	2020-10-02	116.642 mi
Registration #5	2020-10-02	116.642 mi
Registration #6	2021-09-22	141.939 mi
Registration #7	2023-08-03	151.277 mi
Registration #8	2023-08-03	151.277 mi
Registration #9	2023-08-03	151.277 mi
Registration #10	2023-08-03	151.277 mi
Registration #11	2023-08-03	151.277 mi
Registration #12	2023-08-03	151.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2106 mm
Height	1547 mm
Length	4814 mm
Wheel base	2816 mm
Kerb weight	1742 kg
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1360804