

Ford



General information

Make	FORD
Model	TRANSIT 460 H/R BUS 18 STR
Colour	White
Year of manufacture	2016
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP	0 < 101 A
Max. torque	350 Nm	101 - 120 B
Engine capacity	2.198 сс	121 - 140 P
Cylinders	4	141 - 165
Fuel type	Diesel	166 - 185
Consumption city	31.4 mpg	186 - 225
Consumption extra urban	43.5 mpg	225+
Consumption combined	38.2 mpg	



GX66OCF report date: 2024-03-28

Internet history			
Entry 1			
Date	2021-08-1	3	
Pictures	9		
Listing price	View repor	<u>t</u>	
Like me? Finance me	Video viewing with one of our team. Bods a video viewing with one of our team. Bods a video viewing with one of our team. Control viewing with one of our team. Control viewing with one of our team. Control viewing with one of our team.	<image/>	Van NOW, VAT Later Not depositi required until your 3 st payment Motorood Motorood Motorood

source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-28
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	9
Total items failed	2

МОТ #8	2023-09-29 10:46	
MOT test number	679861652903	
Result	🗸 Passed	
Next expiry date 2024-09-2		
Advice Nearside Front Tyre worn close to legal limit/worn on edge & nail (5.2.3 (e))		
Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rearward (5.3.4 (a) (i))		
Advice Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))		

MOT #7	2022-09-23 15:31
MOT test number	899564040827
Result	✓ Passed
Advice Rear Inner Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))	
Advice Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriora	ted (5.3.4 (b) (i))

МОТ #6	2021-09-22 11:57
MOT test number	979385649819
Result	✓ Passed
Minor Offside Rear Inner Tyre obviously under inflated (5.2.3 (I))	





MOT #5	2020-09-15 14:27
MOT test number	689285165329
Result	✓ Passed
MOT #4	2019-09-24 11:58
MOT test number	348216350402
Result	✓ Passed
Minor Nearside Rear reflector defective or damaged by up to 50% of the reflect	ing surface (4.8.1 (a) (i))
MOT #3	2018-09-19 13:29
MOT test number	505415535533
Result	✓ Passed
MOT #2	2017-09-26 15:33
MOT test number	354631641166
Result	✓ Passed
MOT #1	2017-09-04 16:14
MOT test number	537539037567
Result	🗙 Failed
Fail Offside Rear Seat belt retracting mechanism defective (5.2.5b)	

Fail Trailer electrical socket (13 pin) not operating the trailer lamps as intended (1.9.4)



GX66OCF report date: 2024-03-28

Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 October 2024	Expires: 28 September 2024
Tax status	Valid until 1 October
Days left	155
MOT expiry date	28 September 2024
Full MOT history	See MOT history





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-21
Last registration	2023-09-29
Complete history	See info



Registration #1	2016-09-21	22 mi
Registration #2	2017-09-04	7.665 mi
Registration #3	2017-09-26	7.688 mi
Registration #4	2018-09-19	15.432 mi
Registration #5	2019-09-24	22.640 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		10. 200 and

More info >





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight	
Width	2474 mm
Height	2781 mm
Length	6704 mm
Kerb weight	3011 kg
Max. allowed weight	4600 kg
Additional information	
Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	17
Engine number CarCheck.co.uk	GG50482 page 11/11