



General information

Make	VOLKSWAGEN
Model	POLO MATCH (70BHP)
Colour	Silver
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	112 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





## MOT history

MOT expiry date	2020-11-16
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	6
Total items failed	11

MOT #11	2019-05-15 10:30
MOT test number	372483393994
Result	✓ Passed
Next expiry date	2020-11-16

MOT #10	2019-05-15 08:10
MOT test number	613304818240
Result	✗ Failed
Fail	Brake fluid contaminated (1.8 (a))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #9	2018-04-25 13:04
MOT test number	998248184302
Result	✓ Passed

MOT #8	2017-04-24 15:45
MOT test number	821811279551
Result	✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
Advice	Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
Advice	Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #7** 2016-05-17 08:02**MOT test number** 213216862485**Result** ✓ Passed**MOT #6** 2015-09-03 05:59**MOT test number** 832943465149**Result** ✗ Failed

**Fail** Nearside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside rear and offside rear tyres have cracks in the tread

**Fail** Offside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #5** 2015-08-05 14:29**MOT test number** 658847915276**Result** ✓ Passed**MOT #4** 2014-08-06 16:01**MOT test number** 588948114266**Result** ✓ Passed

**Advice** Offside Side repeater has light sources not illuminating, but not more than 50% (1.4.A.2c)

**MOT #3** 2013-08-01 11:32**MOT test number** 369183413239**Result** ✓ Passed**MOT #2** 2012-08-01 15:54**MOT test number** 257144312225**Result** ✓ Passed



MOT #1	2012-08-01 11:48
MOT test number	278264112289
Result	✗ Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Offside Headlamp aim too low (1.8)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Headlamp aim too low (1.8)
Fail	Nearside rear parking brake recording little or no effort (3.7.B.6a)



Tax & MOT check

✖  
Untaxed

Tax expired:  
19 March 2020

✖  
MOT

Expired:  
16 November 2020

Tax status	Expired at 19 March 2020
Days left	1502 days too late
MOT expiry date	16 November 2020
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-08-03
Last registration	2019-05-15
Complete history	<a href="#">See info</a>



Registration #1	2009-08-03	25 mi
Registration #2	2012-08-01	15.632 mi
Registration #3	2012-08-01	15.632 mi
Registration #4	2013-08-01	21.720 mi
Registration #5	2014-08-06	27.955 mi
Registration #6	2015-08-05	33.406 mi
Registration #7	2019-05-15	35.277 mi
Registration #8	2019-05-15	35.277 mi
Registration #9	2019-05-15	35.277 mi
Registration #10	2019-05-15	35.277 mi
Registration #11	2019-05-15	35.277 mi
Registration #12	2019-05-15	35.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

BZG258667