



report date: 2024-03-28

General information

Make	FIAT
Model	500C C LOUNGE
Colour	White
Year of manufacture	2010
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.500 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-06-13
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	31
Total items failed	7

MOT #15	2023-06-14 10:31
MOT test number	338604356385
Result	✓ Passed
Next expiry date	2024-06-13

MOT #14	2022-04-16 12:22
MOT test number	297243540309
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2021-04-20 08:04
MOT test number	817607914559
Result	✓ Passed
Advice	Rear Direction indicator slightly discoloured offside and nearside (4.4.3 (a))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Rear Coil spring corroded offside and nearside (5.3.1 (b) (i))

**MOT #12** 2020-07-11 09:34**MOT test number** 884394875497**Result** ✓ Passed**Advice** Exhaust corroding**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #11** 2019-08-02 15:17**MOT test number** 304416768739**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Exhaust silencer is heavily corroded**MOT #10** 2019-08-02 15:17**MOT test number** 640052932083**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Exhaust silencer is heavily corroded**MOT #9** 2018-09-11 10:25**MOT test number** 392757017568**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #8**

2018-09-10 14:51

**MOT test number**

669501874958

**Result****✗ Failed****Fail**

Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Advice**

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Advice**

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail**

Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Fail**

Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Fail**

Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

**MOT #7**

2017-06-21 14:06

**MOT test number**

509136064918

**Result****✓ Passed****Advice**

Both front tyres worn low

**Advice**

Nearside rear tyre very low on 1.6mm in places

**Advice**

Front brake discs heavily worn/lipped/corroded

**Advice**

Offside rear tyre low

**Advice**

Rear exhaust silencer corroded and slightly leaking

**MOT #6** 2017-06-21 12:34**MOT test number** 533303360004**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear exhaust silencer heavily corroded and slightly leaking
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Tyre worn close to the legal limit nearside rear tyre very low on 1.6mm in places (4.1.E.1)
- Advice** Front brake discs heavily worn/lipped/corroded
- Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Offside Front Tyre worn close to the legal limit worn smooth on extreme inner edge (4.1.E.1)

**MOT #5** 2017-06-21 11:07**MOT test number** 457108378481**Result** ✗ Failed

- Advice** Rear exhaust silencer heavily corroded and slightly leaking
- Advice** Offside Front Tyre worn close to the legal limit worn smooth on extreme inner edge (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake discs heavily worn/lipped/corroded
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Tyre worn close to the legal limit nearside rear tyre very low on 1.6mm in places (4.1.E.1)
- Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #4** 2016-06-02 13:59**MOT test number** 672958219564**Result** ✓ Passed



MOT #3	2015-05-18 16:21
MOT test number	215458535112
Result	✓ Passed
MOT #2	2014-09-15 12:08
MOT test number	996698154216
Result	✓ Passed
MOT #1	2013-08-28 11:34
MOT test number	885350243220
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
13 June 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	13 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-09-24
Last registration	2023-06-14
Complete history	<a href="#">See info</a>



Registration #1	2010-09-24	21 mi
Registration #2	2013-08-28	11.700 mi
Registration #3	2014-09-15	15.061 mi
Registration #4	2015-05-18	17.061 mi
Registration #5	2016-06-02	24.209 mi
Registration #6	2017-06-21	30.833 mi
Registration #7	2017-06-21	30.833 mi
Registration #8	2017-06-21	30.834 mi
Registration #9	2018-09-10	50.644 mi
Registration #10	2019-06-20	50.644 mi
Registration #11	2019-06-20	50.644 mi
Registration #12	2019-06-20	50.644 mi
Registration #13	2019-06-20	50.644 mi
Registration #14	2019-06-20	50.644 mi
Registration #15	2019-06-20	50.644 mi
Registration #16	2019-06-20	50.644 mi
Registration #17	2019-06-20	50.644 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	905 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats 4

<b>Number of axles</b>	2
<b>Engine number</b>	5802608