



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	White
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-09-01
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-11
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	15
Total items failed	9

MOT #12	2024-01-12 14:58
MOT test number	862136888217
Result	✓ Passed
Next expiry date	2025-01-11
Advice	Rear exhaust mount and rear flange corroded
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Both rear seat belts slow to retract
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Advice	Underbody surface corrosion

MOT #11	2022-10-14 09:14
MOT test number	972438416727
Result	✓ Passed

**MOT #10**

2022-10-12 12:24

**MOT test number**

108498516336

**Result****✗ Failed****Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Headlamp levelling device inoperative (4.1.5 (a))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #9**

2021-08-26 14:30

**MOT test number**

376027247558

**Result****✓ Passed****MOT #8**

2020-09-19 11:46

**MOT test number**

287795447971

**Result****✓ Passed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin both rear (1.1.13 (a) (ii))**MOT #7**

2020-09-19 08:54

**MOT test number**

642444546450

**Result****✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Rear Brake pad(s) wearing thin both rear (1.1.13 (a) (ii))**Fail** Front Windscreen wiper does not clear the windscreen effectively both front (3.4 (b) (ii))

**MOT #6** 2019-09-23 08:53**MOT test number** 204623093634**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #5** 2018-09-18 08:02**MOT test number** 430207204602**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #4** 2018-09-18 08:02**MOT test number** 661816640237**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #3** 2017-09-26 09:01**MOT test number** 262734876281**Result** ✓ Passed**MOT #2** 2017-09-19 13:28**MOT test number** 918640677015**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Power steering fluid level below minimum (2.3.1)



MOT #1	2016-09-26 13:03
MOT test number	697064935847
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
11 January 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	11 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>GV62OVK</b>
Plate since	2019-06-29
Current registration	<b>GV62OVK</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-01-24
Last registration	2024-01-12
Complete history	<a href="#">See info</a>



Registration #1	2013-01-24	8 mi
Registration #2	2016-09-26	38.559 mi
Registration #3	2017-09-19	44.721 mi
Registration #4	2017-09-26	44.872 mi
Registration #5	2018-09-18	53.406 mi
Registration #6	2018-09-18	53.406 mi
Registration #7	2019-09-23	60.349 mi
Registration #8	2019-09-23	60.349 mi
Registration #9	2019-09-23	60.349 mi
Registration #10	2019-09-23	60.349 mi
Registration #11	2019-09-23	60.349 mi
Registration #12	2019-09-23	60.349 mi
Registration #13	2019-09-23	60.349 mi
Registration #14	2019-09-23	60.349 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	227236K