



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	VIANO CDI BLUEEFFICIENCY AMBIENTE
Colour	Black
Year of manufacture	2011
Top speed	117 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	100 kW / 136 HP / 163 BHP
Max. torque	360 Nm at 1.600 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	43.5 mpg
Consumption combined	38.7 mpg
CO2 emission	216 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-12-05
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-10-06
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	13
Total items failed	5

MOT #13	2023-10-06 12:52
MOT test number	503839268019
Result	✓ Passed
Next expiry date	2024-10-06

MOT #12	2023-10-05 11:04
MOT test number	451745924311
Result	✗ Failed
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt drop link (5.3.4 (b) (ii))
Fail	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Fuel cap/sealing device ineffective (6.1.3 (b) (i))
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #11	2022-10-06 16:45
MOT test number	491906120442
Result	✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Minor	Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**MOT #10** 2021-10-07 14:35**MOT test number** 557225627483**Result** ✓ Passed**MOT #9** 2020-09-15 12:24**MOT test number** 610407374437**Result** ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))
- Advice** Exhaust middle pipe exhaust clamp slight corroded
- Advice** Rear Suspension unit damaged but not to excess BOTH (5.3.5 (b) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement BOTH (5.3.4 (a) (i))

**MOT #8** 2019-08-08 11:50**MOT test number** 429701319686**Result** ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7** 2018-08-28 12:39**MOT test number** 206479663115**Result** ✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6** 2017-08-24 12:13**MOT test number** 321231095493**Result** ✓ Passed

**MOT #5** 2016-08-12 12:16**MOT test number** 990695252423**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2016-08-12 12:16**MOT test number** 802500565924**Result** ✗ Failed**Pass with rectification** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2015-08-25 11:32**MOT test number** 565980046065**Result** ✓ Passed**MOT #2** 2014-04-02 14:53**MOT test number** 926632694069**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #1** 2012-11-22 17:09**MOT test number** 387667222315**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
6 October 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	6 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history


Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2019-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-01
Last registration	2023-10-06
Complete history	<a href="#">See info</a>



Registration #1	2011-03-01	11 mi
Registration #2	2012-11-22	30.931 mi
Registration #3	2014-04-02	52.896 mi
Registration #4	2015-08-25	87.343 mi
Registration #5	2016-08-12	108.679 mi
Registration #6	2016-08-12	108.679 mi
Registration #7	2017-08-24	129.176 mi
Registration #8	2018-08-28	142.609 mi
Registration #9	2019-08-28	156.042 mi
Registration #10	2020-08-28	169.475 mi
Registration #11	2021-08-28	182.908 mi
Registration #12	2022-08-28	196.341 mi
Registration #13	2023-08-28	209.774 mi
Registration #14	2024-03-28	223.207 mi
Registration #15	2024-03-28	236.640 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1901 mm
Height	1923 mm
Length	5008 mm
Wheel base	3200 mm
Kerb weight	2166 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

**Number of axles**

2

**Engine number**

65194030666108