



report date: 2024-03-29

General information

Make	BMW
Model	316 318D SE
Colour	White
Year of manufacture	2014
Top speed	132 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	118 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-07-02
Pictures	13
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-01
Pictures	13
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-08
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	23
Total items failed	10

MOT #11 2023-07-07 09:35

MOT test number 434531098869

Result ✓ Passed

Next expiry date 2024-07-08

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10 2022-07-07 16:01

MOT test number 508346619479

Result ✓ Passed

MOT #9 2021-07-09 10:27

MOT test number 531485114123

Result ✓ Passed

**MOT #8** 2021-07-07 11:49**MOT test number** 130107518628**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2020-12-30 11:26**MOT test number** 293990025999**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened Nearside front and offside front (1.1.14 (a) (ii))**Advice** Tyre worn close to legal limit/worn on edge NEARSIDE REAR JUST ABOVE THE 1.65MM ALL OVER VERY CLOSE TO LEGAL LIMIT (5.2.3 (e))**Advice** Brake pad(s) wearing thin offside rear (1.1.13 (a) (ii))**MOT #6** 2020-12-30 11:26**MOT test number** 646196342371**Result** ✗ Failed**Pass with rectification** Position lamp not working nearside front (4.2.1 (a) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened Nearside front and offside front (1.1.14 (a) (ii))**Pass with rectification** Position lamp not working offside front (4.2.1 (a) (ii))**Advice** Tyre worn close to legal limit/worn on edge NEARSIDE REAR JUST ABOVE THE 1.65MM ALL OVER VERY CLOSE TO LEGAL LIMIT (5.2.3 (e))**Advice** Brake pad(s) wearing thin offside rear (1.1.13 (a) (ii))**MOT #5** 2019-12-23 15:50**MOT test number** 752589537193**Result** ✓ Passed**Minor** Anti-roll bar linkage ball joint dust cover severely deteriorated nearside front (5.3.4 (b) (ii))

**MOT #4** 2019-12-23 14:34**MOT test number** 196537617159**Result** ✗ Failed**Fail** Tyre tread depth below requirements of 1.6mm offside front (5.2.3 (e))**Minor** Anti-roll bar linkage ball joint dust cover severely deteriorated nearside front (5.3.4 (b) (i))**Fail** Tyre tread depth below requirements of 1.6mm nearside front (5.2.3 (e))**MOT #3** 2018-11-03 11:14**MOT test number** 996655043735**Result** ✓ Passed**MOT #2** 2017-11-04 14:13**MOT test number** 524824615762**Result** ✓ Passed**Advice** Engine covers and under trays fitted**Advice** Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Front Brake pad(s) wearing thin Inner pads look low (3.5.1g)

**MOT #1**

2017-11-04 09:40

MOT test number

479830044618

Result**✗ Failed**

Fail Nearside Front Lower Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Front Brake pad(s) wearing thin Inner pads look low (3.5.1g)

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

Advice Offside aim not checked

Fail Offside Front position lamp(s) not working 434 (1.1.A.3b)

Advice 666/666/334/666 No Spr

Advice Central Items removed from driver's view prior to test

Fail Offside Headlamp not working on dipped beam 477 (1.7.5a)

Fail Nearside Front position lamp(s) not working 434 (1.1.A.3b)

Advice Engine covers and under trays fitted



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
8 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	8 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-11-17
Last registration	2023-07-07
Complete history	See info



Registration #1	2014-11-17	10 mi
Registration #2	2017-11-04	53.655 mi
Registration #3	2017-11-04	53.655 mi
Registration #4	2018-11-03	69.119 mi
Registration #5	2019-12-23	77.213 mi
Registration #6	2019-12-23	77.213 mi
Registration #7	2020-12-30	88.355 mi
Registration #8	2020-12-30	88.355 mi
Registration #9	2020-12-30	88.355 mi
Registration #10	2020-12-30	88.355 mi
Registration #11	2020-12-30	88.355 mi
Registration #12	2020-12-30	88.355 mi
Registration #13	2020-12-30	88.355 mi
Registration #14	2020-12-30	88.355 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1811 mm
Height	1441 mm
Length	4624 mm
Wheel base	2810 mm
Kerb weight	1430 kg
Max. allowed weight	1980 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	79038742