





report date: 2024-03-29

#### General information

Make	RENAULT
Model	CLIO GT LINE TCE
Colour	Blue
Year of manufacture	2018
Top speed	110 mph
0 - 100 km/h	12.2 seconds
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	66 kW / 90 HP / 89 BHP
Max. torque	140 Nm at 2.250 rpm
Engine capacity	898 cc
Cylinders	3
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

### Internet history

#### Entry 2

Date 2022-01-04

Pictures 28

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2022-01-03	
Pictures	2	
Listing price	View report	





source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

# MOT history

MOT expiry date	2024-09-27
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #4	2023-09-13 10:45
MOT test number	604670295397
Result	✓ Passed
Next expiry date	2024-09-27
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #3		2022-09-21 11:23
MOT test	number	230820474662
Result		✓ Passed
Advice	Brake pedal wearing smooth (1.1.2 (c))	
Advice Nearside Front top macpherson strutt mount bearing noisy when rotated lock to lock		
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

2021-09-21 15:07 **MOT #2 MOT** test number 312613964427 ✓ Passed Result **Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) **Advice** Brake pedal wearing smooth (1.1.2 (c)) Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #1		2021-09-21 14:01
MOT test	number	190814226434
Result		<b>×</b> Failed
<b>Fail</b> W	/indscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or co	ords (5.2.3 (d) (i))
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Brake pedal wearing smooth (1.1.2 (c))	
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or core	ds (5.2.3 (d) (i))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cord	ls (5.2.3 (d) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-29

#### Tax & MOT check





Expires: 27 September 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	27 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



HV68XCK report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	history

For how long did the current and previous owner(s) have this RENAULT? How many owne have? Check it in the premium report and see all owner registrations. Download the full re		AULT
***************************************		
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		
Current registration	NK NA	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 9/11



HV68XCK report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-09-28
Last registration	2023-09-13
Complete history	See info



Registration #1	2018-09-28	24 mi
Registration #2	2021-09-21	33.633 mi
Registration #3	2021-09-21	33.633 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



## Dimensions & weight

Width	1945 mm
Height	1448 mm
Length	4062 mm
Wheel base	2589 mm
Kerb weight	1057 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	U352959 page 11/11