





report date: 2024-03-28

General information

Make	MERCEDES-BENZ	
Model	B-CLASS B180 CDI BLUEEFFICIENCY SPORT	
Colour	Blue	
Year of manufacture	2014	
Top speed	118 mph	
0 - 60 mph	11.9 seconds	
Gearbox	7 speed automatic	

Engine & fuel consumption

Power	80 kW / 109 HP / 107 BHP
Max. torque	260 Nm at 2.500 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



KS14PUK

report date: 2024-03-28


Internet history

Entry 1

Date 2022-02-08

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-10
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #10	2024-03-04 15:49
MOT test number	946355989426
Result	✓ Passed
Next expiry date	2025-03-10

MOT #9	2023-03-03 11:27
MOT test number	294858873150
Result	✓ Passed

MOT #8	2022-03-11 18:01
MOT test number	515671026728
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #7 2021-01-22 14:07

MOT test number 433643088786

Result ✓ Passed

Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Supplementary restraint system warning lamp does not illuminate air bag lamp function is normal but dash indicates fault with passenger airbag (7.1.6 (a))

Advice Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2020-01-17 16:51

MOT test number 215733286881

Advice Air bag light is off but there is a warning sign indicates there may be a fault with air bag system

MOT #5 2019-01-22 11:59

MOT test number 297106818057

Result
✓ Passed

MOT #4 2018-09-17 11:07

MOT test number 855053454173

Result

Passed

MOT #3 2018-03-08 13:41

MOT test number 168785766066

CarCheck.co.uk page 4/12



KS14PUK

report date: 2024-03-28

MOT #2

MOT test number

128428708295

Result

Advice O/s/r tyre cracking in treads

MOT #1

MOT test number

979308512459

Result

Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Advice O/s/r tyre cracking in treads

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	10 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



KS14PUK

report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type
Damage 2

Date

Category

Type



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report here .	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK OK
Plate since	
	More info >
	More into /

CarCheck.co.uk page 9/12



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-07-03
Last registration	2024-03-04
Complete history	See info



Registration #1	2014-07-03	12 mi
Registration #2	2017-06-26	38.199 mi
Registration #3	2017-06-26	38.201 mi
Registration #4	2018-03-08	47.326 mi
Registration #5	2018-09-17	54.226 mi
Registration #6	2019-01-22	57.333 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	

The MERCEDES-BENZ factory car options list is only available in the premium report.

View the complete MERCEDES-BENZ factory list for this vehicle <u>here</u>.

More info >

Safety ratings

S0567 S0569

NCAP rating	****
Adult	97%
Children	81%
Pedestrian	56%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2010 mm
Height	1557 mm
Length	4359 mm
Wheel base	2699 mm
Kerb weight	1475 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
	10/10

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	K9KF451D021385