



General information

Make	FIAT
Model	500X MULTIJET CROSS
Colour	White
Year of manufacture	2015
Top speed	115 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 2

Date	2023-12-14
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-06-17
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-10
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	19
Total items failed	8

MOT #8	2023-09-11 14:34
MOT test number	293643241264
Result	✓ Passed
Next expiry date	2024-09-10

MOT #7	2022-08-27 08:46
MOT test number	794930780957
Result	✓ Passed
Advice	Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #6	2021-08-31 13:50
MOT test number	712970913629
Result	✓ Passed

**MOT #5**

2021-08-24 14:15

**MOT test number**

244787616979

**Result****✗ Failed**

- Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure Tyre inner wall (5.2.3 (d) (ii))
- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure Tyre inner wall (5.2.3 (d) (ii))
- Advice** Offside Front Door handle insecure
- Fail** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both side (1.1.14 (a) (ii))

**MOT #4**

2020-12-16 14:45

**MOT test number**

611142895478

**Result****✓ Passed**

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Tyre slightly damaged/cracking or perishing both sides perishing slightly (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #3**

2020-12-09 16:42

**MOT test number**

689208740659

**Result****✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing both sides perishing slightly (5.2.3 (d) (ii))
- Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt insecure (2.1.3 (g) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #2**

2019-12-17 14:31

**MOT test number**

669160886402

**Result****✓ Passed****MOT #1**

2018-12-19 13:47

**MOT test number**

499715934865

**Result****✓ Passed**

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
10 September 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	10 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-12-31
Last registration	2023-09-11
Complete history	<a href="#">See info</a>



Registration #1	2015-12-31	22 mi
Registration #2	2018-12-19	25.188 mi
Registration #3	2019-12-17	31.998 mi
Registration #4	2020-12-09	36.911 mi
Registration #5	2020-12-16	37.007 mi
Registration #6	2020-12-16	37.007 mi
Registration #7	2020-12-16	37.007 mi
Registration #8	2020-12-16	37.007 mi
Registration #9	2020-12-16	37.007 mi
Registration #10	2020-12-16	37.007 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	86%
Children	85%
Pedestrian	74%
Safety systems	64%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1796 mm
Height	1608 mm
Length	4273 mm
Wheel base	2570 mm
Kerb weight	1320 kg
Max. allowed weight	1875 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	7511554