





report date: 2024-03-29

General information

Make	MINI	
Model	COUNTRYMAN COOPER	
Colour	Green	
Year of manufacture	2018	
Top speed	124 mph	
0 - 60 mph	9.7 seconds	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	134 BHP
Max. torque	220 Nm at 4.200 rpm
Engine capacity	1.499 сс
Cylinders	3
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	2.8 mpg
CO2 emission	134 g/km
CO2 label	Е



CarCheck.co.uk page 1/11



Internet history

Entry 1

Elitiy 1	
Date	2021-12-25
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-09-05
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #4	2023-08-30 08:25
MOT test number	478712757543
Result	✓ Passed
Next expiry date	2024-09-05

MOT #3	2022-08-30 09:17
MOT test number	649092371452
Result	✓ Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened slight discs (1.1.14 (a) (ii))	lip to both front brake
Advice Rear Brake pad(s) wearing thin inner brake pad worn to 2mm (1.1.13 (a) (ii))
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened slight discs (1.1.14 (a) (ii))	lip to both rear brake

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #2 2022-08-30 08:19

MOT test number 802659667225

Result X Failed

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Minor Rear Windscreen wiper blade defective wiper blade bent / damaged (3.4 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened slight lip to both rear brake discs (1.1.14 (a) (ii))

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened slight lip to both front brake discs (1.1.14 (a) (ii))

Advice Rear Brake pad(s) wearing thin inner brake pad worn to 2mm (1.1.13 (a) (ii))

MOT #1 2021-08-11 09:04

MOT test number 479329936378

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check





Expires: 5 September 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	5 September 2024
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-09-06
Last registration	2023-08-30
Complete history	See info



Registration #1	2018-09-06	8 mi
Registration #2	2021-08-11	22.649 mi
Registration #3		11.777 esi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		71.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	90%
Children	80%
Pedestrian	64%
Safety systems	51%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1822 mm
Height	1557 mm
Length	4299 mm
Wheel base	2670 mm
Kerb weight	1385 kg
Max. allowed weight	1955 kg

Additional information

Fuel tank capacity	51	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number F533H961