





report date: 2024-03-29

### General information

Make	PEUGEOT
Model	508 HDI SR
Colour	Black
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	72.4 mpg
Consumption combined	58.9 mpg
CO2 emission	125 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-29

# Internet history

### Entry 1

Date 2021-06-19

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-10-16
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	18
Total items failed	5

MOT #12	2023-10-16 09:21
MOT test number	936046411798
Result	<b>✓</b> Passed
Next expiry date	2024-10-16

MOT #11	2022-10-17 10:04
MOT test number	669591451592
Result	<b>√</b> Passed
Advice Offside Rear Tyre worn close to	legal limit/worn on edge (5.2.3 (e))
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice Items removed from driver's vie	w prior to test
Advice Offside Front Lower Suspension (5.3.4 (a) (i))	arm pin or bush worn but not resulting in excessive movement

MOT #10	2021-10-11 13:50
MOT test number	340623298191
Result	<b>✓</b> Passed
MOT #9	2020-06-22 15:03
MOT test number	612178332407
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



SH11WPO report date: 2024-03-29

MOT #8	2019-05-29 14:16
--------	------------------

**MOT test number** 858205792482

MOT #7 2018-05-17 11:16

MOT test number 337172656392

Result 

Passed

**MOT #6** 2017-05-30 12:09

**MOT test number** 431651704702

**Result** 
✓ Passed

Advice NSR drop link has very slight play in a ball joint

**Advice** OSF wishbone bushes deteriorated but not resulting in excess movement

**Advice** Engine covers and under trays fitted

**Advice** Rear heat shield has come adrift

**Advice** NSF tire cut, no cords visible

CarCheck.co.uk page 4/13



report date: 2024-03-29

**MOT #5** 2017-05-29 14:46 717612416654 **MOT** test number Result × Failed **Advice** NSF tire cut, no cords visible Fail Nearside Registration plate lamp not working (1.1.C.1d) Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Advice NSR drop link has very slight play in a ball joint **Advice** OSF wishbone bushes deteriorated but not resulting in excess movement Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b) Engine covers and under trays fitted Advice Advice Rear heat shield has come adrift

MOT #4

MOT test number

762925528750

Result

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Advice Offside Rear tyre low on tread

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #3		2016-05-14 08:35
MOT test	number	334308272402
Result		✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2	2015-05-07 12:29
MOT test number	519357725152
Result	<b>✓</b> Passed
MOT #1	2014-05-29 08:52
MOT test number	266589944445
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

### Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	16 October 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



about of pliates

factor science

# SH11WPO

report date: 2024-03-29

# Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this PEUGEOT had different number plates.

UK C

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 11/13



SH11WPO report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-05-24
Last registration	2023-10-16
Complete history	See info



Registration #1	2011-05-24	6 mi
Registration #2	2014-05-29	54.730 mi
Registration #3	2015-05-07	64.388 mi
Registration #4	2016-05-14	72.454 mi
Registration #5	2017-05-27	80.738 mi
Registration #6	2017-05-29	80.751 mi
Registration #7	2017-05-30	129.929 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 12/13



SH11WPO report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	87%
Pedestrian	41%
Safety systems	97%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1853 mm
Height	1456 mm
Length	4792 mm
Wheel base	2817 mm
Kerb weight	1618 kg
Max. allowed weight	2065 kg

# Additional information

Fuel tank capacity	72	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 pag	je 13/13

Number of axles 2

**Engine number** DYXH4134222