



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 TDI P/V
Colour	White
Year of manufacture	2011
Top speed	98 mph
0 - 60 mph	16.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.9 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-03
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	21
Total items failed	7

MOT #15	2024-01-25 13:32
MOT test number	693388516236
Result	✓ Passed
Next expiry date	2025-02-03

MOT #14	2023-01-25 17:17
MOT test number	883387598290
Result	✓ Passed
Advice	Rear Prop shaft bearing has slight play (6.1.7 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2023-01-25 09:56
MOT test number	480109222172
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Prop shaft bearing has slight play (6.1.7 (b) (i))
Fail	Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #12	2022-02-04 15:33
MOT test number	132720779187
Result	✓ Passed

**MOT #11**

2022-02-02 08:49

MOT test number

565044981938

Result**✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #10**

2020-12-11 08:59

MOT test number

811367295718

Result**✓ Passed****MOT #9**

2020-12-03 10:40

MOT test number

656573945459

Result**✗ Failed****Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Minor** Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #8** 2020-02-03 15:37**MOT test number** 895629538807**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #7** 2019-01-31 12:14**MOT test number** 623807468497**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #6** 2018-02-06 09:07**MOT test number** 866174178390**Result** ✓ Passed**MOT #5** 2017-02-02 12:31**MOT test number** 776771592306**Result** ✓ Passed**MOT #4** 2016-02-03 09:51**MOT test number** 890967736494**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

**MOT #3** 2015-01-05 17:23**MOT test number** 469505505050**Result** ✓ Passed**Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**MOT #2** 2014-01-23 09:02**MOT test number** 837153324040**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2014-01-22 09:27**MOT test number** 317892324094**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
3 February 2025

Tax status		Valid until 1 April
Days left		336
MOT expiry date		3 February 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-21
Last registration	2024-01-25
Complete history	See info



Registration #1	2011-03-21	24 mi
Registration #2	2014-01-22	57.988 mi
Registration #3	2014-01-23	57.988 mi
Registration #4	2015-01-05	80.492 mi
Registration #5	2016-02-03	100.455 mi
Registration #6	2017-02-02	120.577 mi
Registration #7	2018-02-06	129.406 mi
Registration #8	2019-01-31	131.220 mi
Registration #9	2020-02-03	134.235 mi
Registration #10	2020-02-03	134.235 mi
Registration #11	2020-02-03	134.235 mi
Registration #12	2020-02-03	134.235 mi
Registration #13	2020-02-03	134.235 mi
Registration #14	2020-02-03	134.235 mi
Registration #15	2020-02-03	134.235 mi
Registration #16	2020-02-03	134.235 mi
Registration #17	2020-02-03	134.235 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2283 mm
Height	2476 mm
Length	5292 mm
Kerb weight	1912 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	CAA 197076