





report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO BLUEHDI XTR
Colour	Brown
Year of manufacture	2016
Top speed	103 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/12



YK16PXU

report date: 2024-03-28

Internet history

Entry 1

 Date
 2021-01-29

 Pictures
 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-06
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	16
Total items failed	3

MOT #8	2024-03-07 16:19
MOT test number	995057577033
Result	✓ Passed
Next expiry date	2025-03-06

MUI#/	2023-02-17 14:04
MOT test	number 650761271623
Result	✓ Passed
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6		2023-02-17 14:04
MOT test number		600061123577
Result		X Failed
Pass with rectification longer prevents the ingress	•	stant velocity boot split or insecure, no
Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

CarCheck.co.uk page 3/12



MOT #5 2022-01-28 16:29

MOT test number 366164109198

Result Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4 2022-01-27 10:37

MOT test number 889715249348

Result X Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3 2021-02-22 10:01

MOT test number 324801718219

CarCheck.co.uk page 4/12



MOT test number

Result

Advice
Large poppy removed from front grille as covering front registration plate

Items removed from driver's view prior to test dash cam and phone holder

MOT #1	2019-03-07 14:47
MOT test number	846941796611
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

furthe scinors

YK16PXU

report date: 2024-03-28

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes

See in this check if this CITROEN had different number plates.

More info >

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-03-29
Last registration	2024-03-07
Complete history	See info



Registration #1	2016-03-29	10 mi
Registration #2	2019-03-07	31.717 mi
Registration #3	2020-03-12	41.890 mi
Registration #4		11.777 es
Registration #5	2021-02-22	47.783 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 ea
		11.777 es 11.777 es
Registration #7		11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	***
Adult	56%
Children	74%
Pedestrian	63%
Safety systems	48%
Overall rating	59%
Video	see crash video

Dimensions & weight

Width	1810 mm
Height	1852 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1374 kg
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBHB3071188

CarCheck.co.uk page 12/12