




report date: 2024-03-28

General information

Make	VAUXHALL
Model	MERIVA LIFE
Colour	Black
Year of manufacture	2017
Top speed	110 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E







Internet history

Entry 2


Date	2021-09-07
Pictures	10
Listing price	<a href="#">View report</a>



source: autoonline.co.uk

Entry 1

Date	2021-08-23
Pictures	21
Listing price	<a href="#">View report</a>



source: heycar.co.uk



MOT history

MOT expiry date	2025-05-17
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	4
Total items failed	1

<b>MOT #8</b>	2024-04-18 12:55
MOT test number	347214349010
Result	✓ Passed
Next expiry date	2025-05-17

<b>MOT #7</b>	2024-04-18 11:17
MOT test number	806750751241
Result	✗ Failed
<b>MAJOR</b>	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

<b>MOT #6</b>	2023-05-12 08:47
MOT test number	706436198884
Result	✓ Passed

<b>MOT #5</b>	2023-05-10 08:37
MOT test number	150404467108
Result	✗ Failed
<b>MAJOR</b>	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
<b>DANGEROUS</b>	Front Engine mounting bracket fractured (6.1.8 (a) (ii))
<b>Advice</b>	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))



<b>MOT #4</b>	2022-05-10 08:22
<b>MOT test number</b>	147372263805
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2021-05-05 09:59
<b>MOT test number</b>	259084041896
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2020-04-28 09:42
<b>MOT test number</b>	946302529765
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2020-04-28 09:42
<b>MOT test number</b>	372833865571
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 September 2024

✓  
**MOT**

**Expires:**  
17 May 2025

**Tax status** Valid until 1 September

**Days left** 125

**MOT expiry date** 17 May 2025

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>First licence fee (12 months)</b>	£ 255,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner 1	Start	End
Owner 2	Start	End
Owner 3	Start	End
Owner 4	Start	End
Owner 5	Start	End
Owner 6	Start	End

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>SC17WBD</b>
Plate since	2019-09-29
Current registration	<b>SC17WBD</b>
Plate since	2019-09-29

More info >



**Finance check**

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-05-18
Last registration	2024-04-18
Complete history	<a href="#">See info</a>



Registration #1	2017-05-18	11 mi
Registration #2	2020-04-28	23.802 mi
Registration #3	2020-04-28	23.802 mi
Registration #4	2021-05-05	39.449 mi
Registration #5	2022-05-05	55.277 mi
Registration #6	2023-05-05	71.105 mi
Registration #7	2024-05-05	86.933 mi
Registration #8	2025-05-05	102.761 mi
Registration #9	2026-05-05	118.589 mi
Registration #10	2027-05-05	134.417 mi
Registration #11	2028-05-05	150.245 mi

More info >



## Safety ratings

<b>NCAP rating</b>	★★★★★
<b>Adult</b>	89%
<b>Children</b>	77%
<b>Pedestrian</b>	55%
<b>Safety systems</b>	86%
<b>Overall rating</b>	80%
<b>Video</b>	<a href="#">see crash video</a>



## Dimensions & weight

<b>Width</b>	1994 mm
<b>Height</b>	1615 mm
<b>Length</b>	4300 mm
<b>Wheel base</b>	2644 mm
<b>Kerb weight</b>	1376 kg
<b>Max. allowed weight</b>	1905 kg

## Additional information

<b>Fuel tank capacity</b>	54 l
<b>Fuel delivery</b>	Multi-Point Injection
<b>Number of doors</b>	5
<b>Number of seats</b>	5
<b>Number of axles</b>	2
<b>Engine number</b>	B14XER -19PF3548LDD