





report date: 2024-03-28

## General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI S/S ECOFLEX
Colour	White
Year of manufacture	2013
Top speed	97 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	126 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history

### Entry 2

Date 2021-10-30

Pictures 17

Listing price <u>View report</u>









source: yesauto.com

#### Entry 1

Date	2021-10-08
Pictures	12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

# MOT history

MOT expiry date	2025-03-24
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	10
Total items failed	0

MOT #10	2024-03-20 12:59
MOT test number	690185589858
Result	✓ Passed
Next expiry date	2025-03-24
Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated drop lin	k top (5.3.4 (b) (i))
Advice Nearside Rear Tyre worn close to legal limit/worn on edge inner and outer (e))	edge (perrished) (5.2.3
Advice Offside Front top strut mount noisy and rough in rotation	

MOT #9	2023-03-20 15:34
MOT test number	395770197451
Result	✓ Passed
Advice Rear Tyre worn close to legal limit/worn on edge 1856515 (5.2.3 (e))	

MOT #8	2022-03-25 14:24
MOT test number	298551251457
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7	2022-03	3-19 11:19
MOT test	number 1948	88299437
Result		<b>x</b> Failed
<b>Advice</b> adjustmen	Parking brake efficiency only just met. It would appear that the braking system requires at or repair. (1.4.2 (a) (i))	
Advice	Nearside Front tyre started wearing on inner edge	
MAJOR	Nearside Front Headlamp aim not tested (4.1.2 (b))	
Minor	Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))	
Advice	Front wipers smearing	
MAJOR	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #6	2020-10-05 14:06
MOT test number	596570366498
Result	<b>✓</b> Passed
MOT #5	2019-11-27 14:14
MOT test number	107049352984
Result	<b>✓</b> Passed
MOT #4	2018-12-21 14:46
MOT test number	412819036848
Result	<b>✓</b> Passed
MOT #3	2017-12-14 13:48
MOT test number	383673868563
Result	✓ Passed
MOT #2	2016-12-19 13:43
MOT test number	110990655543
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1 2015-12-21 13:49

**MOT test number** 975489673000

**Result** ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	24 March 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

## Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date	
Category	
Туре	

## Damage 2

Date	

#### Category

**Type** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 7/12



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlondere.	
***************************************	
***************************************	
Plate changes	More info >
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK SIN
Plate since	
Current registration	NK SIZ
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-01-14
Last registration	2024-03-20
Complete history	See info



Registration #1	2013-01-14	7 mi
Registration #2	2015-12-21	42.920 mi
Registration #3	2016-12-19	58.121 mi
Registration #4	2017-12-14	72.473 mi
Registration #5	2018-12-21	83.366 mi
Registration #6	2019-11-27	98.495 mi
Registration #7	2020-10-05	104.068 mi
Registration #8		71.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		10.307 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

		_		
I ) I m	ension	c l	MOIG	nt.
	CHSIUH	3 W	welu	III.

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1270 kg
Max. allowed weight	2020 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20004914020 LN9

CarCheck.co.uk page 12/12